



PEACE RIVER REGIONAL DISTRICT



Submission to

**Peace River Regional District**

**Facility Condition Assessment Report  
Moberly Lake Fire Hall**

**Version: Final**

**November 17, 2021**

Prepared by:  
FCAPX a Division of Roth IAMS  
Project No. 21075  
[www.fcapx.com](http://www.fcapx.com)



A Division of Roth IAMS

# Collaborating to Provide Asset Data You Can Trust

## Executive Summary


FCAPX a division of Roth IAMS Ltd. (FCAPX) was retained by the Peace River Regional District (PRRD) to conduct a Facility Condition Assessment (FCA) of the Moberly Lake Fire Hall, BC. The objective of the FCA was to identify, based on current observed conditions, deficiencies and potential lifecycle replacements in the next 30 years.

## Facility Summary

Moberly Lake Fire Hall is located at 6494 Lakeshore Drive in Moberly Lake, BC. This facility is a two-storey structure without a basement, constructed in 1983. An addition was constructed on the west side in 1991. The total gross floor area is estimated to be about 410 SM in size. The building was assessed on June 22, 2021.

## Findings

An analysis of the capital needs by building systems over the next 10 years was created for the building to visually view the replacement/repair forecast.



## Collaborating to Provide Asset Data You Can Trust

The FCA identified repairs and replacements that are anticipated over the next 30 years. The table below summarizes the total capital expenditures (in current year dollars) for the repairs and replacements that are anticipated over the course of the 30-year evaluation period.

| Unifomat Division           | Immediate 2021 | Short Term 2022-2026 | Mid Term 2027-2031 | Long Term 2032-2050 | Totals              |
|-----------------------------|----------------|----------------------|--------------------|---------------------|---------------------|
| A-Substructure              | \$ -           | \$ -                 | \$ -               | \$ -                | \$ -                |
| B- Shell                    | \$ -           | \$ 89,908            | \$ 67,212          | \$ 348,475          | \$ 505,595          |
| C – Interiors               | \$ -           | \$ 38,158            | \$ 93,873          | \$ 191,629          | \$ 323,660          |
| D – Services                | \$ -           | \$ 25,391            | \$ 138,787         | \$ 296,657          | \$ 460,835          |
| E – Equipment & Furnishings | \$ -           | \$ -                 | \$ -               | \$ -                | \$ -                |
| F – Special Construction    | \$ -           | \$ -                 | \$ -               | \$ 9,335            | \$ 9,335            |
| G – Building Sitework       | \$ -           | \$ 57,500            | \$ 208,732         | \$ 461,829          | \$ 728,061          |
| <b>Totals</b>               | <b>\$ 0</b>    | <b>\$ 210,957</b>    | <b>\$ 508,604</b>  | <b>\$ 1,307,925</b> | <b>\$ 2,027,486</b> |

<sup>1</sup>Costs shown above do not include soft costs (engineering design, review, etc.). See section 3.6 for further information.

# Collaborating to Provide Asset Data You Can Trust

## Table of Contents

|     |   |    |
|-----|---|----|
| 1   | Introduction .....                            | 1  |
| 1.1 | Facility .....                                | 1  |
| 1.2 | Site Review .....                             | 1  |
| 1.3 | Owner Supplied Material .....                 | 1  |
| 1.4 | Facility Summary .....                        | 1  |
| 2   | Scope of Work .....                           | 3  |
| 2.1 | Deviations from the Guide .....               | 4  |
| 2.2 | Limiting Conditions .....                     | 5  |
| 3   | Definitions .....                             | 6  |
| 3.1 | Evaluation Period .....                       | 6  |
| 3.2 | Opinions of Probable Costs .....              | 6  |
| 3.3 | Asset Life Expectancy .....                   | 7  |
| 3.4 | Recommendation Type .....                     | 7  |
| 3.5 | Condition Ratings and Site Observations ..... | 8  |
| 3.6 | Factors .....                                 | 8  |
| 4   | Facility Condition Assessment .....           | 10 |
| 4.1 | Facility Condition Index .....                | 10 |
| 5   | Reserve Fund Analysis .....                   | 11 |
| 6   | Floor Plan/Site Plan .....                    | 12 |
| 7   | Preventative Maintenance Plan .....           | 12 |
| 8   | Closure .....                                 | 13 |

## APPENDIX

**Appendix A – Facility Condition Assessment Findings**

**Appendix B – 30-Year Capital Plan Summary**

**Appendix C – Reserve Fund Analysis**

**Appendix D – Floor Plan/Site Plan**

**Appendix E – Preventative Maintenance Plan**

# Collaborating to Provide Asset Data You Can Trust

## 1 INTRODUCTION

---

FCAPX a division of Roth IAMS Ltd. (FCAPX) was retained by the Peace River Regional District (PRRD) to conduct a Facility Condition Assessment (FCA) of Moberly Lake Fire Hall in Moberly Lake, BC (herein referred to as the “Facility, “Site” or “Property”). We understand the purpose of this report is to assist with the long-term capital planning for the facility. This report summarizes the findings of the FCA for the property.

### 1.1 FACILITY

Information on the evaluated facility is provided below:

|  |  |
|--|--|
| <b>Building Name</b>                         | Moberly Lake Fire Hall                 |
| <b>Address</b>                               | 6494 Lakeshore Drive, Moberly Lake, BC |
| <b>Estimated Building Floor Area (sq.m.)</b> | 410                                    |
| <b>Number of Storeys</b>                     | 2                                      |
| <b>Date of Construction</b>                  | 1983                                   |

### 1.2 SITE REVIEW

A site visit was performed on June 22, 2021 by the following FCAPX personnel:

- Brenton Wier, Facility Assessor

### 1.3 OWNER SUPPLIED MATERIAL

In this report, reference is made to the “reported” condition of particular systems and/or components. The reported condition pertains to information provided by the building’s operations and maintenance personnel and/or tenants. In some cases, this information was gathered through either an onsite interview process or a formal off-site interview process.

- No Documents were available for review.

### 1.4 FACILITY SUMMARY

#### 1.4.1 Structural and Architectural Summary

Construction years and the total area of the facility have been estimated based on the data provided by the client. The facility was constructed in parts with the oldest section being constructed circa 1983. The original structure includes a vehicle bay and hose tower. The original building section measures approximately 110 SM. In circa 1991 a section with an additional vehicle bay, an administration area, two washrooms, and an upstairs lunchroom was added on the west side. The approximate area of the 1991 addition is 300 SM. The total building area is approximately 410 SM. The facility sits facing west, with Lakeshore Drive running along the property to the north. The Moberley Lake

Page No: 1

Project No. 21075

© Copyright 2021 FCAPX a Division of Roth IAMS Ltd.- All rights reserved

## Collaborating to Provide Asset Data You Can Trust

Fire Hall sits to the east of the Community Hall. The main entrance is installed on the west elevation of the 1991 building section.

The building is conventional wood framing with a pitched, wood roof clad in metal roofing resting atop a concrete slab-on-grade. Painted metal siding is provided on all exterior elevations. Metal exterior doors are provided at entrances and exits. Interior finishes comprise painted walls, metal wall and ceiling panels, rolled vinyl flooring, wood kitchen cabinets with laminate countertops, and painted ceilings.

### 1.4.2 Plumbing and Mechanical Systems Summary

A buried domestic water feed enters the mechanical room to a pressure tank. Domestic water is provided by an electric domestic hot water heater. Plumbing fixtures include water closets, lavatories, sinks, and showers. The administration areas and washrooms are heated via electric baseboard heaters. The lunchroom is provided with a propane gas-fire forced air furnace. Vehicle bays are heated via electric unit heaters and propane gas-fired radiant tube heaters

### 1.4.3 Electrical Systems Summary

An overhead Single-Phase, 120/240V electrical service terminates to the main disconnect switch installed in the original building section. Power is fed to subdistribution panelboards. Interior lighting is a mix of LED and incandescent fixtures. Exterior lighting is incandescent/LED fixtures. Emergency lighting battery packs and exit lighting are provided. There is an automatic transfer switch that connects to the generator system installed on the exterior south elevation. The generator system also serves the Moberly Lake Community Hall.

### 1.4.4 Site Feature Systems Executive Summary

The gravel roadway that connects Don Phillips Way to Lakeshore Drive to the south is owned and operated by the Fire Hall. There is a gravel parking lot on the west elevation. Concrete barriers are provided at the edge of the parking lot and around the exterior truck fill area. Poured concrete pads are provided at the east and south elevations. A diesel fuel tank with a fill pump is installed south of the facility. There is a buried septic tank south of the facility and a buried domestic water tank installed south of the Moberly Lake Community Hall. Both tanks are owned and operated by the Fire Hall but are shared with Community Hall. There is a buried water tank connecting to a municipally owned cistern on the north side of the facility for truck filling. An overhead electrical service is provided by the local utility.

# Collaborating to Provide Asset Data You Can Trust

## 2 SCOPE OF WORK

---

The FCA carried out by FCAPX is generally based on the ASTM Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process (E2018-15) and consisted of the following:

- Background Information Request and Review;
- Interview(s) with Knowledgeable Site Staff;
- Walk-through Site Assessment Visit;
- Summary of Opinions of Probable Costs to remedy observed physical deficiencies;
- Summary of Opinions of Probable Costs to replace components which will exceed their expected useful life (EUL) over the evaluation period; and
- Preparation of an FCA Report, including salient findings and supporting photographs.

The ASTM defines a physical deficiency as a conspicuous defect or significant deferred maintenance of a site's material systems, components, or equipment as observed during the site assessor's walk-through site visit. Included within this definition are material systems, components, or equipment that are approaching, have reached, or have exceeded their typical expected useful life (EUL) or whose remaining useful life (RUL) should not be relied upon in view of actual or effective age, abuse, excessive wear and tear, exposure to the elements, lack of proper or routine maintenance, etc. This definition specifically excludes deficiencies that may be remedied with routine maintenance, miscellaneous minor repairs, normal operating maintenance, etc., and excludes conditions that generally do not constitute a material physical deficiency of the site.

The review of the Site was based on a visual walk-through review of the visible and accessible components of the property, building and related structures. The roof surface, interior and exterior wall finishes, and floor and ceiling finishes of the on-site building and related structures were visually assessed to determine their condition and to identify physical deficiencies, where observed. The assessment did not include an intrusive investigation of wall assemblies, ceiling cavities, or any other enclosures/assemblies. No physical tests were conducted, and no samples of building materials were collected to substantiate observations made, or for any other reason.

The review of the mechanical systems, electrical systems, and fire & life safety systems at the property included discussions with the site representative and review of pertinent maintenance records that were made available. A visual walk-through assessment of the mechanical systems, electrical systems, and fire & life safety systems was conducted to



## Collaborating to Provide Asset Data You Can Trust

determine the type of systems present, age, and aesthetic condition, with considerations of the reported performance. No physical tests were conducted on these systems.

A detailed evaluation of the property development's compliance with applicable national and/or provincial Building Codes and/or Fire Codes is not part of the scope of this assessment. It is assumed that the existing buildings and related structures were reviewed and approved by local authorities at the time of construction. However, applicable codes may be referenced by FCAPX, at their discretion, to identify deficiencies and appropriate recommendations.

Replacement and repair costs are based on unit rates published by Means Publishing and/or Marshall & Swift Valuation Service, combined with local experience gained by FCAPX. The quantities associated with each item have been estimated during a walk-through site assessment and do not represent exact measurements or quantities. At the time of replacement, specific "scope of work" statements and quotations should be determined, and the budgetary items revised to reflect actual expenditures. Not included are items that would be addressed as routine maintenance. However, the capital costs may include items, which are currently managed under the Operations and Maintenance budget for the site.

Opinions of probable costs for deficiencies that are individually less than the established threshold amount are generally not included in the FCA cost tables. The exception are deficiency costs relating to life, safety or accessibility, these may be included regardless of this cost threshold.

### 2.1 DEVIATIONS FROM THE GUIDE

The major deviations from ASTM E2018-15 for this project that was not included are as follows:

- A review of municipal/public records for zoning;
- A comprehensive building and/or fire & life safety code/regulatory review for compliance. It is assumed that at the time of building construction/commission and/or subsequent renovation(s), a duty of care was undertaken to ensure the building and related structures were constructed in accordance with the current building and fire code, as well as reviewed and approved by the local authorities having jurisdiction;
- An assessment of the property's compliance with barrier-free accessibility requirements; and
- A review of municipal/regional records to determine if the property resides in a designated flood plain.

Furthermore, the FCA did not include a:

Page No: 4

Project No. 21075

© Copyright 2021 FCAPX a Division of Roth IAMS Ltd.- All rights reserved



## Collaborating to Provide Asset Data You Can Trust

- Verification of the number of parking spaces;
- Verification of gross and net usable areas of the site building(s); and
- Review of as-built construction drawings for the building and site.

### 2.2 LIMITING CONDITIONS

This report has been prepared for the exclusive and sole use of the Peace River Regional District (PRRD). The report may not be relied upon by any other person or entity without the express written consent of FCAPX and PRRD.

Any reliance on this report by a third party, any decisions that a third party makes based on this report, or any use at all of this report by a third party is the responsibility of such third parties. FCAPX accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made, or actions taken, based on this report.

The assessment of the building/site components was performed using methods and procedures that are consistent with standard commercial and customary practice as outlined in ASTM Standard E 2018-15 for facility condition assessments. As per this ASTM Standard, the assessment of the building/site components was based on a visual walk-through site visit, which captured the overall condition of the site at that specific point in time only.

No legal surveys, soil tests, environmental assessments, geotechnical assessments, detailed barrier-free compliance assessments, seismic assessments, detailed engineering calculations, or quantity surveying compilations have been made. No responsibility, therefore, is assumed concerning these matters. FCAPX did not design or construct the building(s) or related structures and therefore will not be held responsible for the impact of any design or construction defects, whether or not described in this report. No guarantee or warranty, expressed or implied, with respect to the property, building components, building systems, property systems, or any other physical aspect of the property is made.

The recommendations and our opinion of probable costs associated with these recommendations, as presented in this report, are based on walk-through non-invasive observations of the parts of the building which were readily accessible during our visual review. Conditions may exist that are not as per the general condition of the system being observed and reported in this report. Opinions of probable costs presented in this report are also based on information received during interviews with operations and maintenance staff. In certain instances, FCAPX has been required to assume that the information provided is accurate and cannot be held responsible for incorrect information received during the interview process. Should additional information become available with respect to the condition of the building and/or site elements, FCAPX requests that

## Collaborating to Provide Asset Data You Can Trust

this information be brought to our attention so that we may reassess the conclusions presented herein.

The opinions of probable costs are intended for order of magnitude budgeting purposes only. The scope of work and the actual costs of the work recommended can only be determined after a detailed examination of the element/system in question, understanding of the site restrictions, understanding of the effects on the ongoing operations of the site/building, definition of the construction schedule, and preparation of tender documents. We expressly waive any responsibilities for the effects of any action taken as a result of these endeavors unless we are specifically advised of prior to, and participate in the action, at which time, our responsibility will be negotiated.

Our opinions and recommendations presented in our reports will be rendered in accordance with generally accepted professional standards and are not to be construed as a warranty or guarantee regarding existing or future physical conditions at the Site or regarding compliance of Site systems/components and procedures/operations with the various regulating codes, standards, regulations, ordinances, etc.

### 3 DEFINITIONS

---

The following are definitions to aid in the understanding of the assessment.

#### 3.1 EVALUATION PERIOD

For the purpose of this report, the opinions of probable cost to repair major defects in materials or systems that may significantly affect the value of the property or continued operation of the facilities, and to replace base building equipment/systems that have reached, or may reach their expected useful life, will be a thirty (30) year evaluation period.

#### 3.2 OPINIONS OF PROBABLE COSTS

Opinions of probable costs for repair and/or replacement of components and/or additional investigation of the conditions identified in this report are based on the noted method of evaluation. These opinions are not construction costs and are for general budgeting purposes only since they are based on historical costing information and our experience with similar systems in other buildings. A detailed or exhaustive examination of quantities/costs of equipment, materials, or labour required for the remedial work has not been performed. Unless otherwise stated, engineering costs for remedial work have not been included in this report.

Cost estimates within the report are Class D (+/- 40%).

## Collaborating to Provide Asset Data You Can Trust

Only planned actions with a total cost over \$5,000 have been included in this report. Actions below this cost threshold are assumed to be handled under Operation and Maintenance budgets. Actions relating to life safety may be included in the report, regardless of cost.

As components are replaced they will need to meet current code requirements, therefore, additional costs may be required.

### 3.3 ASSET LIFE EXPECTANCY

The facility systems observed during the assessment were broken down by their major assets and assigned an expected useful life (EUL). This value was used to determine the remaining useful life (RUL) of the asset. The values for EUL are based on information provided in manufacturer's literature, industry standards, our observations of the assets, and our experience with similar materials and systems in similar locales. Based on the asset's overall reported and/or observed physical condition an "Equivalent Age" was determined that represents the point within the asset's lifecycle based on the EUL. This was then used to determine the RUL.

The EUL of assets is a theoretical number, which is an estimate, that is a function of quality of materials used, manufacturing and installation, as well as frequency and intensity of service, the degree of maintenance afforded to the asset, and local weather conditions.

The realization of an asset's EUL does not necessarily constitutes its replacement. A detailed condition assessment or investigation is recommended as a prudent approach to confirm the component RUL and the need for either a repair (maintenance) or a refurbishment. Risk, including safety or the cost of damage to the facility and its use, was considered in estimating the RUL and the schedule for major repairs or replacements.

### 3.4 RECOMMENDATION TYPE

Recommendation types in this report indicate the action that is to take place based on the review of the component. The recommendation type categories are shown below.

- **Study:** Includes recommendations for further investigation into the condition or options for determining the appropriate repair/replacement action.
- **Major Repair:** Any component or system in which future major repair is anticipated but not replacement of the entire component.
- **Lifecycle Replacement:** Any component or system in which future full replacement is anticipated.

## Collaborating to Provide Asset Data You Can Trust

### 3.5 CONDITION RATINGS AND SITE OBSERVATIONS

ASTM defines “physical deficiencies” as “the presence of conspicuous defects or material deferred maintenance of a subject property’s material systems, components, or equipment as observed during the field observer’s walk-through survey. Included within this definition are material systems, assets, or equipment that is approaching, has reached, or has exceeded its typical expected useful life (EUL) or whose remaining useful life (RUL) should not be relied upon in view of actual or effective age, abuse, excessive wear and tear, lack of proper maintenance, etc. This specifically excludes deficiencies that may be remediated with routine maintenance or miscellaneous minor repairs and excludes conditions that generally do not constitute a material physical deficiency of the site.

The physical condition of major facility / site systems and assets is dependent on whether a physical deficiency is associated with that asset / system. The physical condition of assets / systems noted in this report have been rated as either “Critical”, “Poor”, “Fair”, “Good”, or “Excellent”. Definitions for these ratings are provided below.

- 1- EXCELLENT: The component is new and no immediate concerns are evident.
- 2- GOOD: No immediate concerns are evident. The components appear to meet all present requirements and to be adequately maintained. Replacement anticipated in 6 years or beyond.
- 3- FAIR: The medium level condition rating. Generally, components meet present requirements and have been adequately maintained. Some minor deficiencies may be noted. A repair or lifecycle replacement is anticipated within the evaluation period between 3-5 years.
- 4- POOR: The component is not able to meet current requirements and has significant deficiencies. Generally, components may have failed, may be at or near the end of their service life, or may exhibit evidence of deterioration or insufficient maintenance. Recommendations may include urgent repair, replacement or upgrades within 1-2 years.
- 5- CRITICAL: Generally, components may have failed resulting in a high risk of injury, health and safety concerns, or critical system failure. Recommendations for urgent repair, replacement or upgrades are anticipated within the year (<12 months).

### 3.6 FACTORS

Difficulty – used to adjust the unit costs of the component based on its size, construction, etc. compared to the standard criteria for that component.

Regional – used to adjust the component costs based on the building’s geographical location within the Province and Country. Regional factors were provided by PRRD.

Page No: 8

Project No. 21075

© Copyright 2021 FCAPX a Division of Roth IAMS Ltd.- All rights reserved

## Collaborating to Provide Asset Data You Can Trust

Soft Costs – Engineering or Architectural design fees, engineering review fees, etc. This factor is set to 1 when soft costs are not included in the component's replacement costs. Typically, soft costs are required for large projects involving the replacement of several components at the same time (i.e. Heating System). As the FCA separates components into individual replacements, soft costs have not been included.

# Collaborating to Provide Asset Data You Can Trust

## 4 FACILITY CONDITION ASSESSMENT

Herein we present the findings of our assessment, based on the Scope of Work outlined in this report. The Facility Condition Assessment & Opinion of Probable Cost is included in Appendix A. Appendix B contains the Capital Planning Table.

### 4.1 FACILITY CONDITION INDEX

The Facility Condition Index (FCI) gives an indication of a building or portfolio's overall condition. The value is based on a 0-100%+ scale and is derived by dividing the repair costs for a facility by a Current Replacement Value (CRV). The FCI is calculated using only the current condition values, not taking into account the future needs identified in the life cycle evaluation. Site and miscellaneous items are removed from this calculation as the focus is on the building itself.

The overall condition is based on Table 1 below. It should be noted that there is no industry standard for the overall building condition based on a 5-Year FCI. The condition categories are recommendations to be considered.

| Table 1: FCI Condition Categories |                       |
|-----------------------------------|-----------------------|
| 5-year Calculated FCI             | Condition Category    |
| 0% to 10%                         | Good                  |
| 11% to 20%                        | Fair                  |
| 21% to 50%                        | Poor                  |
| >50%                              | Prohibitive to Repair |

The 5-Year FCI is calculated as follows:

$$\text{5-Year FCI} = \frac{\text{Sum of 5-Year Renewal Need for the Building}}{\text{Current Replacement Value of the Building}} \times 100$$

$$\text{5-Year FCI} = \frac{\$129,559}{\$1,612,500} \times 100$$

$$\text{5-Year FCI} = 8\%$$

The 5-Year Renewal Need is the sum of renewal costs recommended in the next 5 years to keep the building functional, and does not consider soft cost factor, criticality, available budget or capital planning decisions made. The total 5-Year Renewal Need cost, (2021-2025) excluding the renewal costs for the site features (roadways, parking lot, walkways,

## Collaborating to Provide Asset Data You Can Trust

etc.) for the subject building is \$129,559. The building Current Replacement Value (CRV) was estimated based on Marshall and Swift insurable value. For the subject building the CRV (or Cost of Reproduction New (CRN)) was determined to be \$1,612,500. The subject building 5-year Facility Condition Index (FCI), calculated based on the 5-Year Renewal Need is 8%. Based on the table above, the FCI suggests that the building is in Good condition overall.

### 5 RESERVE FUND ANALYSIS

---

The scope of work of the review of the Moberly Lake Fire Hall includes the review of the Asset Management Reserve Fund (AMRF) to ensure funding levels meet the required amounts.

Moberly Lake Fire Hall does not currently contribute annually to the fund. Cashflow Scenario 0 presented in this report shows the fund balance with no contributions. Cashflow Scenario 1 presented in this report shows the recommended annual contribution and one-time contributions to an AMRF to ensure funding is available for capital replacement projects in future years.

The cashflow projection considers the following:

- The cashflow scenario is based on the inflated FCA expenditures anticipated during the 30-year evaluation period.
- An annual inflation rate of **2.00%** has been applied to adjust projected replacement costs over the course of the evaluation period.
  - o It must be appreciated that both inflation and interest rates can be volatile due to a number of factors such as global business cycles, the state of the economy, and government policies.
- A positive closing balance was maintained in the AMRF.
- A 2021 AMRF Opening Balance of \$274,135 (Provided by PRRD).
- The 2021 Expenditures from the AMRF are nil.
- It should be appreciated that the accuracy of this projected cash flow decreases toward the end of the 30-year period as a result of uncertainties related to the economy, interest and inflation rates, annual contributions and future replacement costs.
- Annual expenditures as per the findings of the FCA (of note only expenditures over \$5,000 were included).
- Annual inflation rate of 2.0% applied to the estimated FCA expenditures.



## Collaborating to Provide Asset Data You Can Trust

- The AMRF is assumed to earn 2.0% interest.

The projections included in this table are estimates only, based on the information available at the time of preparation. The condition assessment must be updated regularly as the actual figures will vary from the amounts detailed in this table due to changes in interest rates, inflation rates and scheduling of the repair/replacement work.

The reserve fund scenario is included in Appendix C.

### 6 FLOOR PLAN/SITE PLAN

---

A floor plan displaying the basic layout of the facility has been provided in Appendix D.

A site plan has been provided in Appendix D indicating the site boundary for the facility.

### 7 PREVENTATIVE MAINTENANCE PLAN

---

The compiled Preventative Maintenance Plan (PMP) for this facility are presented in Appendix E.

In general, the PMP provides a list of industry standard maintenance tasks for pertinent equipment and systems observed at the time of the facility condition assessment. In addition, the task list also includes recommendations on the amount of time that should be budgeted for each task, and the required skill sets and/or recommendations for the staff who should conduct the tasks.

It is the responsibility of the building owner to ensure that any federal, provincial, and municipal legislative requirements regarding preventative maintenance tasks are being complied with, including but not limited to; requirements enacted by those authorities having jurisdiction, changes over time to code requirements, and the licensing/training of technicians.

# Collaborating to Provide Asset Data You Can Trust

## 8 CLOSURE

---

This report has been prepared for the use of the Peace River Regional District as part of the due diligence process regarding the noted property, and no representations are made by FCAPX to any party other than Peace River Regional District.

Prepared by,

**Brenton Wier**

Facility Assessor

Phone: 587-441-1577, ext. 216

Email: brenton.wier@rothiams.com

**Meaghen Figg-Derksen, P. Tech. (Eng.)**

Facility Assessor

Phone: 587-441-1577, ext. 225

Email: Meaghen.derksen@rothiams.com

Reviewed by,

**Mike Plomske, P.Eng.**

Technical Reviewer

Phone: 587-441-1577, ext. 211

Email: Mike.plomske@rothiams.com

**Curtis Loblick, P.Eng., CEM**

Vice President, Western Canada

Phone: 587-441-1577, ext. 204

Email: curtis.loblick@rothiams.com

**Collaborating to Provide Asset Data You Can Trust**

**APPENDIX A**  
**Facility Condition Assessment**

**Project No. 21075**

© Copyright 2021 FCAPX a Division of Roth IAMS Ltd.- All rights reserved



## A Substructure

### A10 Foundations

| Element Description                       |                                |
|---|--------------------------------|
| Name                                      | A101001 - Standard Foundations |
| Installation Year                         | 1983                           |
| Condition                                 | 2 - Good                       |
| Expected Useful Life                      | 75 Years                       |
| Remaining Useful Life                     | 37 Years                       |
| Renewal Year                              | 2058                           |
| Quantity / Unit of Measure                | 150 / LM Footprint             |
| Unit Cost                                 | \$984.00                       |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1               |
| Replacement Cost                          | \$275,569.20                   |

#### Description

Construction drawings were not available for review during the assessment. While concealed from view below-grade, standard foundations for the building are presumably composed of cast-in-place concrete foundation walls and strip footings on the building perimeter.

#### Condition Narrative

No major deficiencies were observed or reported. It is understood that the original building was constructed in 1983, and the west addition was constructed in 1999. As the remaining useful life falls outside the evaluation window for the oldest installed section, this system has been combined using the oldest known install date (1983).

| Element Description                       |                         |
|---|-------------------------|
| Name                                      | A103001 - Slab on Grade |
| Installation Year                         | 1983                    |
| Condition                                 | 2 - Good                |
| Expected Useful Life                      | 75 Years                |
| Remaining Useful Life                     | 37 Years                |
| Renewal Year                              | 2058                    |
| Quantity / Unit of Measure                | 330 / SM Footprint      |
| Unit Cost                                 | \$71.33                 |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1        |
| Replacement Cost                          | \$43,947.13             |

### Description

A cast-in-place concrete slab-on-grade floor is constructed throughout the building. The slab is presumably reinforced with conventional steel.


### Condition Narrative

No major deficiencies were observed or reported. It is understood that the original building was constructed in 1983, and the west addition was constructed in 1999. As the remaining useful life falls outside the evaluation window for the oldest installed section, this system has been combined using the oldest known install date (1983).

### Photos



Moberly Lake Fire Hall - A103001



Moberly Lake Fire Hall - A103001

**B Shell**  
**B10 Superstructure**

| Element Description                       |                     |
|---|---------------------|
| Name                                      | B103001 - Structure |
| Installation Year                         | 1983                |
| Condition                                 | 3 - Fair            |
| Expected Useful Life                      | 75 Years            |
| Remaining Useful Life                     | 37 Years            |
| Renewal Year                              | 2058                |
| Quantity / Unit of Measure                | 410 / SM Building   |
| Unit Cost                                 | \$280.00            |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1    |
| Replacement Cost                          | \$214,331.60        |

### Description

While concealed from view, the building structure is presumably composed of wood decking that is supported by wood trusses, beams, and perimeter wood stud framework. A hose tower is installed east of the laundry room. The building was constructed in parts with the oldest built circa 1983, housing a vehicle bay and hose tower. The 1999 addition features an additional vehicle bay, administration offices, washrooms, and an upstairs lunchroom and lounge.

### Condition Narrative

No major deficiencies were observed or reported, however, the wood ladder and wood platforms constructed within the hose tower are reportedly unsafe. As a result, the hose tower is not in use. It is recommended to provide an automated winch system for the hose drying tower to eliminate the need to climb the tower. Unsafe wood infrastructure should be removed. A cost to provide an automated hoist system has been provided. Additionally, in the 1999 vehicle bay, there is a through-wall penetration lined with galvanized ductwork that should be investigated. If used for combustion air, it is recommended to install a grill or fan as a maintenance activity. The Fire Chief indicated onsite that the tower could be removed altogether as it has not been in use for several years with no impact on operations. As the remaining useful life falls outside the evaluation window for the oldest installed section, this system has been combined using the oldest known install date (1983).

### Photos



Moberly Lake Fire Hall - B103001



Moberly Lake Fire Hall - B103001



Moberly Lake Fire Hall - B103001

## Recommendations

| Recommendations #1 - Hose Tower - Install Automated Winch / Remove Wood Ladders and Platforms |              |
|---|--------------|
| Type  | Major Repair |
| Year  | 2022         |
| Cost  | \$10,000.00  |

Remove the wood ladder and platforms and install an automated winch system for the hose drying tower.



## B20 Exterior Enclosure

| Element Description                       |                                   |
|---|-----------------------------------|
| Name                                      | B201010 - Exterior Coatings/Paint |
| Installation Year                         | 1999                              |
| Condition                                 | 4 - Poor                          |
| Expected Useful Life                      | 10 Years                          |
| Remaining Useful Life                     | 1 Year                            |
| Renewal Year                              | 2022                              |
| Quantity / Unit of Measure                | 750 / SM                          |
| Unit Cost                                 | \$40.00                           |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                  |
| Replacement Cost                          | \$56,010.00                       |

### Description

Exterior sheet metal siding and the trim around overhead doors are provided with a paint finish.

### Condition Narrative

The paint is worn and sun-damaged. The paint is thin in spots. Lifecycle replacement is recommended to preserve the metal siding.

### Photos



Moberly Lake Fire Hall - B201010



Moberly Lake Fire Hall - B201010



Moberly Lake Fire Hall - B201010

## Recommendations

| Recommendations #1 - Exterior Coatings/Paint |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2022                   |
| Cost   | \$56,010.00            |

Replace Exterior Coatings/Paint

| Element Description                       |                        |
|---|------------------------|
| Name                                      | B201024 - Metal Siding |
| Installation Year                         | 1999                   |
| Condition                                 | 2 - Good               |
| Expected Useful Life                      | 40 Years               |
| Remaining Useful Life                     | 18 Years               |
| Renewal Year                              | 2039                   |
| Quantity / Unit of Measure                | 750 / SM               |
| Unit Cost                                 | \$160.00               |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1       |
| Replacement Cost                          | \$224,040.00           |

### Description

All exterior elevations are provided with vertically-corrugated, sheet metal siding.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - B201024



Moberly Lake Fire Hall - B201024



Moberly Lake Fire Hall - B201024

## Recommendations

| Recommendations #1 - Metal Siding |                        |
|-----------------------------------|------------------------|
| Type                              | Life Cycle Replacement |
| Year                              | 2039                   |
| Cost                              | \$224,040.00           |

Replace Metal Siding

| Element Description                       |                   |
|---|-------------------|
| Name                                      | B202001 - Windows |
| Installation Year                         | 1999              |
| Condition                                 | 2 - Good          |
| Expected Useful Life                      | 35 Years          |
| Remaining Useful Life                     | 13 Years          |
| Renewal Year                              | 2034              |
| Quantity / Unit of Measure                | 7 / SM            |
| Unit Cost                                 | \$950.00          |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1  |
| Replacement Cost                          | \$12,415.55       |

### Description

There are two (2) fixed windows installed on the main floor. There are fixed and operable sash windows installed on the upper south elevation in the lunchroom. Windows are vinyl and contain insulating glazing units. The main floor windows feature security bars.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - B202001



Moberly Lake Fire Hall - B202001



Moberly Lake Fire Hall - B202001

## Recommendations

| Recommendations #1 - Windows |                        |
|------------------------------|------------------------|
| Type                         | Life Cycle Replacement |
| Year                         | 2034                   |
| Cost                         | \$12,415.55            |

Replace Windows

| Element Description                       |                                       |
|---|---------------------------------------|
| Name                                      | B203022 - Overhead Doors - Industrial |
| Installation Year                         | 2003                                  |
| Condition                                 | 2 - Good                              |
| Expected Useful Life                      | 25 Years                              |
| Remaining Useful Life                     | 7 Years                               |
| Renewal Year                              | 2028                                  |
| Quantity / Unit of Measure                | 3 / Each                              |
| Unit Cost                                 | \$12,000.00                           |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                      |
| Replacement Cost                          | \$67,212.00                           |

### Description

There are three (3) sectional metal overhead doors installed on the building's east and west elevations to serve the vehicle bays. The doors feature automatic door openers and glazing inserts.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - B203022



Moberly Lake Fire Hall - B203022



Moberly Lake Fire Hall - B203022



## Recommendations

| Recommendations #1 - Overhead Doors - Industrial |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2028                   |
| Cost   | \$67,212.00            |

Replace Overhead Doors - Industrial

| Element Description                       |                                      |
|---|--------------------------------------|
| Name                                      | B203023 - Single Door - Hollow Metal |
| Installation Year                         | 1983                                 |
| Condition                                 | 3 - Fair                             |
| Expected Useful Life                      | 30 Years                             |
| Remaining Useful Life                     | 5 Years                              |
| Renewal Year                              | 2026                                 |
| Quantity / Unit of Measure                | 4 / Each                             |
| Unit Cost                                 | \$3,200.00                           |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                     |
| Replacement Cost                          | \$23,897.60                          |

## Description

Hollow metal swing-type doors set in pressed metal frames are installed on the building's north, south, and west elevations.

## Condition Narrative

No major deficiencies were observed or reported, however, some doors are marked as exit doors, yet do not have panic hardware. It is recommended to install panic hardware on these doors to meet requirements for emergency exit doors. The cost to complete these repairs is presumed to fall below the cost threshold for repair recommendations (\$5,000) and should be completed as a routine maintenance activity. Doors were installed between 1983 and 1999. The components have surpassed their expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies.

## Photos



Moberly Lake Fire Hall - B203023



Moberly Lake Fire Hall - B203023



Moberly Lake Fire Hall - B203023

## Recommendations

| Recommendations #1 - Single Door - Hollow Metal |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2026                   |
| Cost  | \$23,897.60            |

Replace Single Door - Hollow Metal

## B30 Roofing

| Element Description                       |                         |
|---|-------------------------|
| Name                                      | B301028 - Metal Roofing |
| Installation Year                         | 2019                    |
| Condition                                 | 1 - Excellent           |
| Expected Useful Life                      | 40 Years                |
| Remaining Useful Life                     | 38 Years                |
| Renewal Year                              | 2059                    |
| Quantity / Unit of Measure                | 370 / SM                |
| Unit Cost                                 | \$280.00                |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1        |
| Replacement Cost                          | \$193,421.20            |

### Description

The pitched roof is clad in sheet metal roofing. The roof assembly includes perforated metal soffits, and metal fascia at roof edges. Metal gutters and downspouts are installed at roof edges.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - B301028



Moberly Lake Fire Hall - B301028

## C Interiors

### C10 Interior Construction

| Element Description                       |                            |
|---|----------------------------|
| Name                                      | C101001 - Fixed Partitions |
| Installation Year                         | 1983                       |
| Condition                                 | 2 - Good                   |
| Expected Useful Life                      | 75 Years                   |
| Remaining Useful Life                     | 37 Years                   |
| Renewal Year                              | 2058                       |
| Quantity / Unit of Measure                | 410 / SM Building          |
| Unit Cost                                 | \$95.00                    |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1           |
| Replacement Cost                          | \$72,719.65                |

### Description

Interior fixed partitions are assumed to consist of gypsum-clad wood stud assemblies. Ceilings are provided with a gypsum board finish in the administration area, utility rooms, and the lunchroom.

### Condition Narrative

No major deficiencies were observed or reported. As the remaining useful life falls outside the evaluation window for the oldest installed section, this system has been combined using the oldest known install date (1983). It is recommended to conduct a Hazardous Materials Assessment based on the age of the building. A cost to complete the assessment has been provided herein.

### Photos



Moberly Lake Fire Hall - C101001



Moberly Lake Fire Hall - C101001

### Recommendations

| Recommendations #1 - Hazardous Materials Assessment |                   |
|---|-------------------|
| Type  | Engineering Study |
| Year  | 2024              |
| Cost  | \$5,000.00        |

Undertake a hazardous materials assessment.

| Element Description                       |                            |
|---|----------------------------|
| Name                                      | C101005 - Interior Windows |
| Installation Year                         | 1999                       |
| Condition                                 | 2 - Good                   |
| Expected Useful Life                      | 75 Years                   |
| Remaining Useful Life                     | 53 Years                   |
| Renewal Year                              | 2074                       |
| Quantity / Unit of Measure                | 6 / SM                     |
| Unit Cost                                 | \$600.00                   |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1           |
| Replacement Cost                          | \$6,721.20                 |

### Description

Interior vinyl windows are installed in the second-floor lunchroom to overlook the vehicle bay in the 1999 building section.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - C101005

| Element Description                       |                              |
|---|------------------------------|
| Name                                      | C102022 - Single Door - Wood |
| Installation Year                         | 1999                         |
| Condition                                 | 2 - Good                     |
| Expected Useful Life                      | 40 Years                     |
| Remaining Useful Life                     | 18 Years                     |
| Renewal Year                              | 2039                         |
| Quantity / Unit of Measure                | 9 / Each                     |
| Unit Cost                                 | \$2,000.00                   |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1             |
| Replacement Cost                          | \$33,606.00                  |

### Description

Swing-type wood doors set in wood or metal frames are installed throughout the building. The lunchroom door is a wood french door with glass inserts.


### Condition Narrative

No major deficiencies were observed or reported during the assessment. It is assumed that the majority of interior doors were installed in 1999.


### Photos



Moberly Lake Fire Hall - C102022



Moberly Lake Fire Hall - C102022



Moberly Lake Fire Hall - C102022



## Recommendations

| Recommendations #1 - Single Door - Wood |                        |
|---|------------------------|
| Type                                    | Life Cycle Replacement |
| Year                                    | 2039                   |
| Cost                                    | \$33,606.00            |

Replace Single Door - Wood

| Element Description                       |                               |
|---|-------------------------------|
| Name                                      | C103009 - Cabinets - Kitchens |
| Installation Year                         | 1983                          |
| Condition                                 | 2 - Good                      |
| Expected Useful Life                      | 35 Years                      |
| Remaining Useful Life                     | 6 Years                       |
| Renewal Year                              | 2027                          |
| Quantity / Unit of Measure                | 4 / LM                        |
| Unit Cost                                 | \$1,500.00                    |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1              |
| Replacement Cost                          | \$11,202.00                   |

### Description

There are base and wall-mounted wood-framed cabinets with wood panels and laminate countertops installed in the lunchroom.

### Condition Narrative

No major deficiencies were observed or reported. The components have surpassed their expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies.

### Photos



Moberly Lake Fire Hall - C103009

### Recommendations

| Recommendations #1 - Cabinets - Kitchens |                        |
|--|------------------------|
| Type                                     | Life Cycle Replacement |
| Year                                     | 2027                   |
| Cost                                     | \$11,202.00            |

Replace Cabinets - Kitchens

| Element Description                       |                    |
|---|--------------------|
| Name                                      | C103010 - Vanities |
| Installation Year                         | 1999               |
| Condition                                 | 2 - Good           |
| Expected Useful Life                      | 25 Years           |
| Remaining Useful Life                     | 6 Years            |
| Renewal Year                              | 2027               |
| Quantity / Unit of Measure                | 2 / LM             |
| Unit Cost                                 | \$600.00           |
| Difficulty / Regional / Soft Cost Factors | 2.00 / 1.867 / 1   |
| Replacement Cost                          | \$4,480.80         |

## Description

There are base-mounted wood-framed vanities with pressed wood panels installed in the washrooms.

## Condition Narrative

No major deficiencies were observed or reported during the assessment. The components have surpassed their expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies. The cost factor has been increased due to the type of vanity construction.

## Photos



Moberly Lake Fire Hall - C103010

## Recommendations

| Recommendations #1 - Vanities |                        |
|-------------------------------|------------------------|
| Type                          | Life Cycle Replacement |
| Year                          | 2027                   |
| Cost                          | \$4,480.80             |

Replace Vanities

| Element Description                       |                              |
|---|------------------------------|
| Name                                      | C103011 - Cabinets - General |
| Installation Year                         | 1999                         |
| Condition                                 | 2 - Good                     |
| Expected Useful Life                      | 35 Years                     |
| Remaining Useful Life                     | 13 Years                     |
| Renewal Year                              | 2034                         |
| Quantity / Unit of Measure                | 20 / LM                      |
| Unit Cost                                 | \$1,200.00                   |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1             |
| Replacement Cost                          | \$44,808.00                  |

### Description

There are base and wall-mounted storage partitions installed to line the apparatus floor. Racking is a mix of painted metal or wood.

### Condition Narrative

No major deficiencies were observed or reported. The cost factor has been increased due to the type of vanity construction.

### Photos



Moberly Lake Fire Hall - C103011



Moberly Lake Fire Hall - C103011

### Recommendations

| Recommendations #1 - Cabinets - General |                        |
|---|------------------------|
| Type                                    | Life Cycle Replacement |
| Year                                    | 2034                   |
| Cost                                    | \$44,808.00            |

Replace Cabinets - General

## C20 Stairs

| Element Description                       |                                       |
|---|---------------------------------------|
| Name                                      | C201001 - Interior Stair Construction |
| Installation Year                         | 1999                                  |
| Condition                                 | 2 - Good                              |
| Expected Useful Life                      | 75 Years                              |
| Remaining Useful Life                     | 53 Years                              |
| Renewal Year                              | 2074                                  |
| Quantity / Unit of Measure                | 16 / Per Riser                        |
| Unit Cost                                 | \$800.00                              |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                      |
| Replacement Cost                          | \$23,897.60                           |

### Description

Wood-framed close-backed stairs are installed to provide access to the lunchroom. The staircase features wall-mounted wood handrails. The stairs are provided with a paint finish.

### Condition Narrative

No major deficiencies were observed or reported during the assessment.

### Photos



Moberly Lake Fire Hall - C201001

| Element Description                       |                                       |
|---|---------------------------------------|
| Name                                      | C201002 - Exterior Stair Construction |
| Installation Year                         | 1999                                  |
| Condition                                 | 2 - Good                              |
| Expected Useful Life                      | 40 Years                              |
| Remaining Useful Life                     | 18 Years                              |
| Renewal Year                              | 2039                                  |
| Quantity / Unit of Measure                | 20 / Per Riser                        |
| Unit Cost                                 | \$1,000.00                            |
| Difficulty / Regional / Soft Cost Factors | 0.50 / 1.867 / 1                      |
| Replacement Cost                          | \$18,670.00                           |

## Description

Wood-framed open-backed stairs to grade from the lunchroom on the building exterior. The staircase features base-mounted wood guardrails. An upper landing is supported by wood posts.

## Condition Narrative

No major deficiencies were observed or reported during the assessment, however, it is recommended to paint the stairs to preserve the wood finish. The cost adjustment factor has been decreased to account for the wood construction.

## Photos



Moberly Lake Fire Hall - C201026



Moberly Lake Fire Hall - C201026

## Recommendations

| Recommendations #1 - Exterior Stair Construction |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2039                   |
| Cost   | \$18,670.00            |

Replace Exterior Stair Construction

## C30 Interior Finishes

| Element Description                       |                               |
|---|-------------------------------|
| Name                                      | C301005 - Paint Wall Covering |
| Installation Year                         | 2017                          |
| Condition                                 | 2 - Good                      |
| Expected Useful Life                      | 10 Years                      |
| Remaining Useful Life                     | 6 Years                       |
| Renewal Year                              | 2027                          |
| Quantity / Unit of Measure                | 160 / SM Building             |
| Unit Cost                                 | \$40.00                       |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1              |
| Replacement Cost                          | \$11,948.80                   |

### Description

Interior walls in the administration area, washrooms, utility rooms, and lunchroom are provided with a paint finish.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - C301005



Moberly Lake Fire Hall - C301005

### Recommendations

| Recommendations #1 - Paint Wall Covering |                        |
|--|------------------------|
| Type                                     | Life Cycle Replacement |
| Year                                     | 2027                   |
| Cost                                     | \$11,948.80            |

Replace Paint Wall Covering



| Element Description                       |   |
|---|---|
| Name                                      | C301099 - Other Wall Finishes - Metal Wall Finish |
| Installation Year                         | 1999  |
| Condition                                 | 2 - Good  |
| Expected Useful Life                      | 30 Years  |
| Remaining Useful Life                     | 8 Years   |
| Renewal Year                              | 2029  |
| Quantity / Unit of Measure                | 1 / Lump Sum                                      |
| Unit Cost                                 | \$5,000.00  |
| Difficulty / Regional / Soft Cost Factors | 5.00 / 1.867 / 1                                  |
| Replacement Cost                          | \$46,675.00                                       |


### Description

The 1999 vehicle bay interior walls and ceilings are provided with a sheet metal finish.

### Condition Narrative

No major deficiencies were observed or reported. Unit cost has been determined based on \$100/SM of the vehicle bays (250 SM). The average install date is estimated circa 1999.

### Photos



Moberly Lake Fire Hall - C301099



Moberly Lake Fire Hall - C301099

### Recommendations

| Recommendations #1 - Other Wall Finishes |                        |
|--|------------------------|
| Type                                     | Life Cycle Replacement |
| Year                                     | 2029                   |
| Cost                                     | \$46,675.00            |

Replace Other Wall Finishes



| Element Description                       |   |
|---|---|
| Name                                      | C302007 - Painted / Sealed Concrete Floor |
| Installation Year                         | 2012                                      |
| Condition                                 | 2 - Good                                  |
| Expected Useful Life                      | 15 Years                                  |
| Remaining Useful Life                     | 6 Years                                   |
| Renewal Year                              | 2027                                      |
| Quantity / Unit of Measure                | 262 / SM                                  |
| Unit Cost                                 | \$40.00                                   |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                          |
| Replacement Cost                          | \$19,566.16                               |

### Description

Vehicle bays and mechanical room floors are provided with a paint finish on concrete floor surfaces.


### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - C302007



Moberly Lake Fire Hall - C302007

### Recommendations

| Recommendations #1 - Painted / Sealed Concrete Floor |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2027                   |
| Cost   | \$19,566.16            |

Replace Painted / Sealed Concrete Floor

| Element Description                       |                             |
|---|-----------------------------|
| Name                                      | C302023 - Vinyl Sheet Floor |
| Installation Year                         | 1999                        |
| Condition                                 | 3 - Fair                    |
| Expected Useful Life                      | 15 Years                    |
| Remaining Useful Life                     | 3 Years                     |
| Renewal Year                              | 2024                        |
| Quantity / Unit of Measure                | 148 / SM                    |
| Unit Cost                                 | \$120.00                    |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1            |
| Replacement Cost                          | \$33,157.92                 |

### Description

The administration area, washrooms, and lunchroom are provided with a rolled vinyl floor with welded seams.

### Condition Narrative

The flooring has exceeded its expected useful life and is exhibiting wear and tear that is consistent with age including separating at seams, lifting, and worn finishes in high traffic areas. Lifecycle replacement is recommended.

### Photos



Moberly Lake Fire Hall - C302023



Moberly Lake Fire Hall - C302023

### Recommendations

| Recommendations #1 - Vinyl Sheet Floor |                        |
|--|------------------------|
| Type                                   | Life Cycle Replacement |
| Year                                   | 2024                   |
| Cost                                   | \$33,157.92            |

Replace Vinyl Sheet Floor

| Element Description                       |                                      |
|---|--------------------------------------|
| Name                                      | C303006 - Painted Ceiling Structures |
| Installation Year                         | 2017                                 |
| Condition                                 | 2 - Good                             |
| Expected Useful Life                      | 15 Years                             |
| Remaining Useful Life                     | 11 Years                             |
| Renewal Year                              | 2032                                 |
| Quantity / Unit of Measure                | 160 / SM                             |
| Unit Cost                                 | \$30.00                              |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                     |
| Replacement Cost                          | \$8,961.60                           |


### Description

The ceilings in administration areas, washrooms, utility rooms, and the lunchroom are provided with a paint finish.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - C303006

### Recommendations

| Recommendations #1 - Painted Ceiling Structures |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2032                   |
| Cost  | \$8,961.60             |

Replace Painted Ceiling Structures

## D Services D20 Plumbing

| Element Description                       |                         |
|---|-------------------------|
| Name                                      | D201001 - Water Closets |
| Installation Year                         | 1999                    |
| Condition                                 | 2 - Good                |
| Expected Useful Life                      | 35 Years                |
| Remaining Useful Life                     | 13 Years                |
| Renewal Year                              | 2034                    |
| Quantity / Unit of Measure                | 2 / Each                |
| Unit Cost                                 | \$1,000.00              |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1        |
| Replacement Cost                          | \$3,734.00              |

### Description

There are two (2) floor-mounted vitreous china water closets with flush tanks installed in the washrooms.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D201001



Moberly Lake Fire Hall - D201001

### Recommendations

| Recommendations #1 - Water Closets |                        |
|------------------------------------|------------------------|
| Type                               | Life Cycle Replacement |
| Year                               | 2034                   |
| Cost                               | \$3,734.00             |

Replace Water Closets

| Element Description                       |                      |
|---|----------------------|
| Name                                      | D201003 - Lavatories |
| Installation Year                         | 1999                 |
| Condition                                 | 2 - Good             |
| Expected Useful Life                      | 35 Years             |
| Remaining Useful Life                     | 13 Years             |
| Renewal Year                              | 2034                 |
| Quantity / Unit of Measure                | 2 / Each             |
| Unit Cost                                 | \$1,000.00           |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1     |
| Replacement Cost                          | \$3,734.00           |


### Description

There are two (2) single-piece vanity countertops with an integrated lavatory installed in the washrooms. The lavatories each include a manually operated tap-set.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D201003

### Recommendations

| Recommendations #1 - Lavatories |                        |
|---------------------------------|------------------------|
| Type                            | Life Cycle Replacement |
| Year                            | 2034                   |
| Cost                            | \$3,734.00             |

Replace Lavatories

| Element Description                       |                  |
|---|------------------|
| Name                                      | D201004 - Sinks  |
| Installation Year                         | 1999             |
| Condition                                 | 2 - Good         |
| Expected Useful Life                      | 35 Years         |
| Remaining Useful Life                     | 13 Years         |
| Renewal Year                              | 2034             |
| Quantity / Unit of Measure                | 1 / Each         |
| Unit Cost                                 | \$1,000.00       |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1 |
| Replacement Cost                          | \$1,867.00       |

### Description

There is a dual-basin stainless steel sink with a manually operated tap-set installed in the lunchroom.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D201004

### Recommendations

| Recommendations #1 - Sinks |                        |
|----------------------------|------------------------|
| Type                       | Life Cycle Replacement |
| Year                       | 2034                   |
| Cost                       | \$1,867.00             |

Replace Sinks



| Element Description                       |                           |
|---|---------------------------|
| Name                                      | D201012 - Shower Assembly |
| Installation Year                         | 1999                      |
| Condition                                 | 2 - Good                  |
| Expected Useful Life                      | 25 Years                  |
| Remaining Useful Life                     | 6 Years                   |
| Renewal Year                              | 2027                      |
| Quantity / Unit of Measure                | 2 / Each                  |
| Unit Cost                                 | \$3,000.00                |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1          |
| Replacement Cost                          | \$11,202.00               |

### Description

There are two (2) individual fibreglass shower assemblies installed in the washrooms. Showers feature through-wall valve sets, showerheads, and swinging glass doors.

### Condition Narrative

The components have surpassed their expected useful life, however, due to limited or less than average use, they remain in good condition. Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies.

### Photos




Moberly Lake Fire Hall - D201012



Moberly Lake Fire Hall - D201012



Moberly Lake Fire Hall - D201012



Moberly Lake Fire Hall - D201012

## Recommendations

| Recommendations #1 - Shower Assembly |                        |
|--------------------------------------|------------------------|
| Type                                 | Life Cycle Replacement |
| Year                                 | 2027                   |
| Cost                                 | \$11,202.00            |

Replace Shower Assembly



| Element Description                       |                           |
|---|---------------------------|
| Name                                      | D201016 - Custodial Sinks |
| Installation Year                         | 1999                      |
| Condition                                 | 2 - Good                  |
| Expected Useful Life                      | 30 Years                  |
| Remaining Useful Life                     | 8 Years                   |
| Renewal Year                              | 2029                      |
| Quantity / Unit of Measure                | 2 / Each                  |
| Unit Cost                                 | \$2,000.00                |
| Difficulty / Regional / Soft Cost Factors | 0.25 / 1.867 / 1          |
| Replacement Cost                          | \$1,867.00                |

### Description

There are two (2) free-standing fibreglass utility sinks installed in the laundry room. Each sink is provided with a manually operated tap-set.

### Condition Narrative

No major deficiencies were observed or reported. The cost factor has been decreased to account for the type of sinks.

### Photos



Moberly Lake Fire Hall - D201016

### Recommendations

| Recommendations #1 - Custodial Sinks |                        |
|--------------------------------------|------------------------|
| Type                                 | Life Cycle Replacement |
| Year                                 | 2029                   |
| Cost                                 | \$1,867.00             |

Replace Custodial Sinks

| Element Description                       |   |
|---|---|
| Name                                      | D202001 - Domestic Water Pipes and Fittings |
| Installation Year                         | 1983  |
| Condition                                 | 2 - Good                                    |
| Expected Useful Life                      | 40 Years                                    |
| Remaining Useful Life                     | 6 Years                                     |
| Renewal Year                              | 2027  |
| Quantity / Unit of Measure                | 410 / SM Building                           |
| Unit Cost                                 | \$40.00                                     |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                            |
| Replacement Cost                          | \$30,618.80                                 |

## Description

A buried water service connects the shared exterior buried domestic water tank to domestic water equipment in the mechanical room. Domestic water is distributed via a mix of copper and cross-linked polyethylene (PEX) piping. Firefighting water is fed from a municipally-owned cistern located off-property. Piping enters the west end of the 1999 vehicle bay and includes a fill valve with a flexible hose.

## Condition Narrative

No major deficiencies were observed or reported. A large portion of the domestic water piping was replaced in 2017. The components have surpassed their expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies.

## Photos



Moberly Lake Fire Hall - D202001



Moberly Lake Fire Hall - D202001

## Recommendations

| Recommendations #1 - Domestic Water Pipes and Fittings |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2027                   |
| Cost   | \$30,618.80            |

Replace Domestic Water Pipes and Fittings

| Element Description                       |  |
|---|--|
| Name                                      | D202006 - Domestic Water Booster Systems/Pumps |
| Installation Year                         | 2017   |
| Condition                                 | 2 - Good                                       |
| Expected Useful Life                      | 20 Years                                       |
| Remaining Useful Life                     | 16 Years                                       |
| Renewal Year                              | 2037   |
| Quantity / Unit of Measure                | 1 / Each                                       |
| Unit Cost                                 | \$10,000.00                                    |
| Difficulty / Regional / Soft Cost Factors | 0.20 / 1.867 / 1                               |
| Replacement Cost                          | \$3,734.00                                     |

### Description

There is a domestic water pump installed in the mechanical room to pull water from the exterior buried domestic water tank. The pump is rated at 1/2 HP and is manufactured by Diamond.

### Condition Narrative

No major deficiencies were observed or reported. The difficulty factor has been decreased to account for the size of the pump.

### Photos



Moberly Lake Fire Hall - D202006



Moberly Lake Fire Hall - D202006

### Recommendations

| Recommendations #1 - Domestic Water Booster Systems/Pumps |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2037                   |
| Cost  | \$3,734.00             |

Replace Domestic Water Booster Systems/Pumps

| Element Description                       |  |
|---|--|
| Name                                      | D202008 - Domestic Water Expansion Tanks/Pressure Tank |
| Installation Year                         | 2017   |
| Condition                                 | 2 - Good   |
| Expected Useful Life                      | 30 Years   |
| Remaining Useful Life                     | 26 Years   |
| Renewal Year                              | 2047   |
| Quantity / Unit of Measure                | 1 / Each   |
| Unit Cost                                 | \$4,000.00   |
| Difficulty / Regional / Soft Cost Factors | 0.40 / 1.867 / 1                                       |
| Replacement Cost                          | \$2,987.20   |

### Description

There is a residential-grade pressure tank installed in the mechanical room.


### Condition Narrative

No major deficiencies were observed or reported. The difficulty factor has been decreased to account for the residential grade equipment.

### Photos



Moberly Lake Fire Hall - D202008



Moberly Lake Fire Hall - D202008



Moberly Lake Fire Hall - D202008

## Recommendations

| Recommendations #1 - Domestic Water Expansion Tanks/Pressure Tank |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2047                   |
| Cost  | \$2,987.20             |

Replace Domestic Water Expansion Tanks/Pressure Tank

| Element Description                       |   |
|---|---|
| Name                                      | D202035 - Electric Domestic Water Heaters (Residential Tank Type) |
| Installation Year                         | 2017  |
| Condition                                 | 2 - Good  |
| Expected Useful Life                      | 12 Years  |
| Remaining Useful Life                     | 8 Years   |
| Renewal Year                              | 2029  |
| Quantity / Unit of Measure                | 175 / Liter   |
| Unit Cost                                 | \$25.00   |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1  |
| Replacement Cost                          | \$8,168.13  |

## Description

There is an electric domestic water heater installed in the mechanical room. It is manufactured by GSW (Model: 6ET175PS) and has a tank capacity of 175 litres. The heating input rating is 3000 Watts.


## Condition Narrative

No major deficiencies were observed or reported.

## Photos



Moberly Lake Fire Hall - D202035



Moberly Lake Fire Hall - D202035

## Recommendations

| Recommendations #1 - Electric Domestic Water Heaters (Residential Tank Type) |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2029                   |
| Cost   | \$8,168.13             |

Replace Electric Domestic Water Heaters (Residential Tank Type)



| Element Description                       |  |
|---|--|
| Name                                      | D203001 - Sanitary Waste and Vent Piping |
| Installation Year                         | 1983                                     |
| Condition                                 | 2 - Good                                 |
| Expected Useful Life                      | 50 Years                                 |
| Remaining Useful Life                     | 12 Years                                 |
| Renewal Year                              | 2033                                     |
| Quantity / Unit of Measure                | 410 / SM Building                        |
| Unit Cost                                 | \$45.00                                  |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                         |
| Replacement Cost                          | \$34,446.15                              |


### Description

Sanitary waste and vent piping is ABS and connects fixtures and floor drains to a common drain line that is directed to the site septic tank.


### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D203001



Moberly Lake Fire Hall - D203001

### Recommendations

| Recommendations #1 - Sanitary Waste and Vent Piping |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2033                   |
| Cost  | \$34,446.15            |

Replace Sanitary Waste and Vent Piping

| Element Description                       |                               |
|---|-------------------------------|
| Name                                      | D203007 - Interceptor Systems |
| Installation Year                         | 1999                          |
| Condition                                 | 2 - Good                      |
| Expected Useful Life                      | 25 Years                      |
| Remaining Useful Life                     | 6 Years                       |
| Renewal Year                              | 2027                          |
| Quantity / Unit of Measure                | 2 / Each                      |
| Unit Cost                                 | \$10,000.00                   |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1              |
| Replacement Cost                          | \$37,340.00                   |

### Description

There is an inceptor system installed in the 1983 vehicle bay. It is assumed that a second interceptor is installed in the 1991 bay, though it was covered by a parked truck.

### Condition Narrative

No major deficiencies were observed or reported. The majority of the system is concealed from view. The components are nearing their expected useful life and should therefore be inspected by a qualified tradesperson to determine piping and basin integrity. The cost to complete this inspection is presumed to fall below the cost threshold for repair recommendations (\$5,000) and therefore should be completed as a maintenance activity. In the absence of observed or reported deficiencies, the Remaining Useful Life has been extended.

### Photos



Moberly Lake Fire Hall - D203007

### Recommendations

| Recommendations #1 - Interceptor Systems |                        |
|--|------------------------|
| Type                                     | Life Cycle Replacement |
| Year                                     | 2027                   |
| Cost                                     | \$37,340.00            |

Replace Interceptor Systems



## D30 HVAC

| Element Description                       |                              |
|---|------------------------------|
| Name                                      | D301002 - Gas Supply Systems |
| Installation Year                         | 1983                         |
| Condition                                 | 2 - Good                     |
| Expected Useful Life                      | 40 Years                     |
| Remaining Useful Life                     | 6 Years                      |
| Renewal Year                              | 2027                         |
| Quantity / Unit of Measure                | 410 / SM                     |
| Unit Cost                                 | \$20.00                      |
| Difficulty / Regional / Soft Cost Factors | 0.61 / 1.867 / 1             |
| Replacement Cost                          | \$9,338.73                   |

### Description

There is a steel piped propane gas distribution system to provide propane gas to gas-fired mechanical equipment. Propane is delivered via a tank located on the site grounds. The regulator valve is installed on the exterior north elevation.

### Condition Narrative

No major deficiencies were observed or reported, however, exterior sections of gas piping should be inspected/tested by a qualified technician due to the presence of oxidation on the piping. Once inspected/tested, piping should be repainted as a maintenance activity. The cost to assess/test and repaint exterior sections of piping is presumed to fall below the cost threshold for repair recommendations (\$5,000) and should therefore be completed as a maintenance activity. In the absence of significant deficiencies being observed or reported, lifecycle replacement has been deferred. The exterior propane tank is utility-owned and operated and is not included within this report. The cost adjustment factor has been reduced to account for the limited amount of gas-fired equipment.

### Photos



Moberly Lake Fire Hall - D203001

## Recommendations

| Recommendations #1 - Gas Supply Systems |                        |
|---|------------------------|
| Type                                    | Life Cycle Replacement |
| Year                                    | 2027                   |
| Cost                                    | \$9,338.73             |

Replace Gas Supply Systems

| Element Description                       |   |
|---|---|
| Name                                      | D302003 - Fuel Fired Forced Air Furnace |
| Installation Year                         | 1999                                    |
| Condition                                 | 4 - Poor                                |
| Expected Useful Life                      | 18 Years                                |
| Remaining Useful Life                     | 1 Year                                  |
| Renewal Year                              | 2022                                    |
| Quantity / Unit of Measure                | 60 / MBH                                |
| Unit Cost                                 | \$40.00                                 |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                        |
| Replacement Cost                          | \$4,480.80                              |

## Description

There is a propane gas-fired forced-air furnace installed to provide heating and ventilation to the lunchroom. It is manufactured by American Standard (Model: AUD060C924H3) and has a heating input rating of 60 MBH.

## Condition Narrative

The furnace has exceeded its expected useful life and is exhibiting wear and tear that is consistent with age including loud operation and presumed loss of efficiency. Lifecycle replacement is recommended.

## Photos



Moberly Lake Fire Hall - D302003



Moberly Lake Fire Hall - D302003



Moberly Lake Fire Hall - D302003

## Recommendations

| Recommendations #1 - Fuel Fired Forced Air Furnace |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2022                   |
| Cost   | \$4,480.80             |

Replace Fuel Fired Forced Air Furnace

| Element Description                       |   |
|---|---|
| Name                                      | D302032 - Fuel-Fired Radiant Tube Heaters |
| Installation Year                         | 1999                                      |
| Condition                                 | 3 - Fair                                  |
| Expected Useful Life                      | 18 Years                                  |
| Remaining Useful Life                     | 3 Years                                   |
| Renewal Year                              | 2024                                      |
| Quantity / Unit of Measure                | 2 / Each                                  |
| Unit Cost                                 | \$5,000.00                                |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                          |
| Replacement Cost                          | \$18,670.00                               |

### Description

There are two (2) propane gas-fired radiant tube heaters installed in the vehicle bays. Technical specifications are not available.

### Condition Narrative

No major deficiencies were observed or reported, however, the equipment has exceeded its expected useful life and therefore has a higher likelihood of failure. Lifecycle replacement is recommended.

### Photos



Moberly Lake Fire Hall - D302032



Moberly Lake Fire Hall - D302032

### Recommendations

| Recommendations #1 - Fuel-Fired Radiant Tube Heaters |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2024                   |
| Cost   | \$18,670.00            |

Replace Fuel-Fired Radiant Tube Heaters

| Element Description                       |                                    |
|---|------------------------------------|
| Name                                      | D304001 - Air Distribution Systems |
| Installation Year                         | 1999                               |
| Condition                                 | 2 - Good                           |
| Expected Useful Life                      | 50 Years                           |
| Remaining Useful Life                     | 28 Years                           |
| Renewal Year                              | 2049                               |
| Quantity / Unit of Measure                | 80 / SM Building                   |
| Unit Cost                                 | \$120.00                           |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                   |
| Replacement Cost                          | \$17,923.20                        |

### Description

There is low velocity galvanized steel ductwork installed to provide ventilation in the lunchroom. Ductwork terminates in floor-mounted deflecting diffusers.

### Condition Narrative

No major deficiencies were observed or reported. There was a noted lack of make-up air and exhaust systems present in vehicle bays. It is recommended to consult with local authorities having jurisdiction to ensure that existing infrastructure provides adequate airflow/air exchange in vehicle bays.

### Photos



Moberly Lake Fire Hall - D304001

### Recommendations

| Recommendations #1 - Air Distribution Systems |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2049                   |
| Cost  | \$17,923.20            |

Replace Air Distribution Systems

| Element Description                       |   |
|---|---|
| Name                                      | D304033 - Exhaust Fan - Ceiling (Residential) |
| Installation Year                         | 2003  |
| Condition                                 | 2 - Good                                      |
| Expected Useful Life                      | 25 Years                                      |
| Remaining Useful Life                     | 7 Years                                       |
| Renewal Year                              | 2028  |
| Quantity / Unit of Measure                | 2 / Each                                      |
| Unit Cost                                 | \$1,000.00                                    |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                              |
| Replacement Cost                          | \$3,734.00                                    |

### Description

There are ceiling-mounted residential grade exhaust fans installed in the washrooms. Technical specifications are not available.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D304033

### Recommendations

| Recommendations #1 - Exhaust Fan - Ceiling (Residential) |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2028                   |
| Cost   | \$3,734.00             |

Replace Exhaust Fan - Ceiling (Residential)



| Element Description                       |                                   |
|---|-----------------------------------|
| Name                                      | D305009 - Unit Heaters (Electric) |
| Installation Year                         | 1999                              |
| Condition                                 | 2 - Good                          |
| Expected Useful Life                      | 18 Years                          |
| Remaining Useful Life                     | 6 Years                           |
| Renewal Year                              | 2027                              |
| Quantity / Unit of Measure                | 2 / Each                          |
| Unit Cost                                 | \$2,500.00                        |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                  |
| Replacement Cost                          | \$9,335.00                        |


### Description

There are two (2) suspended electric unit heaters installed in the 1983 vehicle bay. Technical specifications are not available.

### Condition Narrative

No major deficiencies were observed or reported. The components have surpassed their expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies, likely due to the limited use of the heater.

### Photos



Moberly Lake Fire Hall - D305009

### Recommendations

| Recommendations #1 - Unit Heaters (Electric) |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2027                   |
| Cost   | \$9,335.00             |

Replace Unit Heaters (Electric)

| Element Description                       |                                      |
|---|--------------------------------------|
| Name                                      | D305010 - Electric Baseboard Heaters |
| Installation Year                         | 1999                                 |
| Condition                                 | 4 - Poor                             |
| Expected Useful Life                      | 18 Years                             |
| Remaining Useful Life                     | 1 Year                               |
| Renewal Year                              | 2022                                 |
| Quantity / Unit of Measure                | 4 / Each                             |
| Unit Cost                                 | \$300.00                             |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                     |
| Replacement Cost                          | \$2,240.40                           |

### Description

The administration area and the washrooms are provided with electric baseboard heaters.

### Condition Narrative

No major deficiencies were observed or reported, however, the baseboards have exceeded their expected useful life and should therefore be replaced.

### Photos



Moberly Lake Fire Hall - D305010



Moberly Lake Fire Hall - D305010

### Recommendations

| Recommendations #1 - Electric Baseboard Heaters |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2022                   |
| Cost  | \$2,240.40             |

Replace Electric Baseboard Heaters

## D40 Fire Protection

| Element Description                       |                              |
|---|------------------------------|
| Name                                      | D403002 - Fire Extinguishers |
| Installation Year                         | 2017                         |
| Condition                                 | 2 - Good                     |
| Expected Useful Life                      | 10 Years                     |
| Remaining Useful Life                     | 6 Years                      |
| Renewal Year                              | 2027                         |
| Quantity / Unit of Measure                | 410 / SM Building            |
| Unit Cost                                 | \$1.00                       |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1             |
| Replacement Cost                          | \$765.47                     |

### Description

There are wall-mounted ABC-type fire extinguishers installed throughout the building.

### Condition Narrative

No major deficiencies were observed or reported. Annual inspection tags appeared to be up to date.

### Photos



Moberly Lake Fire Hall - D403002



Moberly Lake Fire Hall - D403002

### Recommendations

| Recommendations #1 - Fire Extinguishers |                        |
|---|------------------------|
| Type                                    | Life Cycle Replacement |
| Year                                    | 2027                   |
| Cost                                    | \$765.47               |

Replace Fire Extinguishers

## D50 Electrical

| Element Description                       |   |
|---|---|
| Name                                      | D501005 - Panelboards up to 400A - 1983 |
| Installation Year                         | 1983                                    |
| Condition                                 | 2 - Good                                |
| Expected Useful Life                      | 40 Years                                |
| Remaining Useful Life                     | 6 Years                                 |
| Renewal Year                              | 2027                                    |
| Quantity / Unit of Measure                | 1 / Each                                |
| Unit Cost                                 | \$5,000.00                              |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                        |
| Replacement Cost                          | \$9,335.00                              |

### Description

There is a 120/240V panelboard installed on the south elevation of the 1983 vehicle bay. The amperage reading is not available.


### Condition Narrative

No major deficiencies were observed or reported, however, it is recommended to include breaker schedules in the panels as a maintenance activity. The component has surpassed its expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies.

### Photos



Moberly Lake Fire Hall - D501005



Moberly Lake Fire Hall - D501005

### Recommendations

| Recommendations #1 - Panelboards up to 400A |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2027                   |
| Cost  | \$9,335.00             |

Replace Panelboards up to 400A

| Element Description                       |   |
|---|---|
| Name                                      | D501005 - Panelboards up to 400A - 2015 |
| Installation Year                         | 2015                                    |
| Condition                                 | 2 - Good                                |
| Expected Useful Life                      | 40 Years                                |
| Remaining Useful Life                     | 34 Years                                |
| Renewal Year                              | 2055                                    |
| Quantity / Unit of Measure                | 1 / Each                                |
| Unit Cost                                 | \$5,000.00                              |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                        |
| Replacement Cost                          | \$9,335.00                              |

### Description

There is a 120/240V panelboard installed in the administration area. It is manufactured by Siemens and contains a 100A main breaker.

### Condition Narrative

No major deficiencies were observed or reported, however, the panel is blocked by server equipment. Server equipment should be relocated as a maintenance activity.

### Photos



Moberly Lake Fire Hall - D501005



Moberly Lake Fire Hall - D501005



Moberly Lake Fire Hall - D501005



| Element Description                       |                                       |
|---|---------------------------------------|
| Name                                      | D501025 - LV Main Service Disconnects |
| Installation Year                         | 1983                                  |
| Condition                                 | 2 - Good                              |
| Expected Useful Life                      | 40 Years                              |
| Remaining Useful Life                     | 6 Years                               |
| Renewal Year                              | 2027                                  |
| Quantity / Unit of Measure                | 1 / Each                              |
| Unit Cost                                 | \$10,000.00                           |
| Difficulty / Regional / Soft Cost Factors | 0.30 / 1.867 / 1                      |
| Replacement Cost                          | \$5,601.00                            |

## Description

The main disconnect switch is installed on the south wall in the 1983 vehicle bay. It is manufactured by Square D and is rated for 200A at 240V.

## Condition Narrative

No major deficiencies were observed or reported during the assessment. The difficulty factor has been lowered to account for the size of the switch. The component has surpassed its expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies.

## Photos



Moberly Lake Fire Hall - D501025



Moberly Lake Fire Hall - D501025

## Recommendations

| Recommendations #1 - LV Main Service Disconnects |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2027                   |
| Cost   | \$5,601.00             |

Replace LV Main Service Disconnects

| Element Description                       |                                     |
|---|-------------------------------------|
| Name                                      | D502001 - Branch Wiring and Devices |
| Installation Year                         | 1983                                |
| Condition                                 | 2 - Good                            |
| Expected Useful Life                      | 50 Years                            |
| Remaining Useful Life                     | 12 Years                            |
| Renewal Year                              | 2033                                |
| Quantity / Unit of Measure                | 410 / SM Building                   |
| Unit Cost                                 | \$95.00                             |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                    |
| Replacement Cost                          | \$72,719.65                         |

### Description

Branch wiring consists of a mix of residential-grade and commercial-grade wiring which terminates to electrical distribution panelboards and terminal components, including stratification fans in the apparatus bay. Branch wiring is primarily hidden within wall and ceiling finishes.

### Condition Narrative

No major deficiencies were observed or reported, however, the plug installed over the sink in the kitchen should be replaced with a GFCI rated plug as a maintenance activity.

### Photos



Moberly Lake Fire Hall - D502001



Moberly Lake Fire Hall - D502001

### Recommendations

| Recommendations #1 - Branch Wiring and Devices |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2033                   |
| Cost   | \$72,719.65            |

Replace Branch Wiring and Devices



| Element Description                       |                             |
|---|-----------------------------|
| Name                                      | D502002 - Interior Lighting |
| Installation Year                         | 2019                        |
| Condition                                 | 1 - Excellent               |
| Expected Useful Life                      | 35 Years                    |
| Remaining Useful Life                     | 33 Years                    |
| Renewal Year                              | 2054                        |
| Quantity / Unit of Measure                | 410 / SM Building           |
| Unit Cost                                 | \$85.00                     |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1            |
| Replacement Cost                          | \$65,064.95                 |

### Description

Interior lighting is primarily provided via ceiling-mounted LED fixtures. Lighting in the washrooms and stairwell is provided via incandescent fixtures. There is a 4-lamp halogen fixture installed in the kitchenette in the lunchroom.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D502002



Moberly Lake Fire Hall - D502002

| Element Description                       |                             |
|---|-----------------------------|
| Name                                      | D502041 - Exterior Lighting |
| Installation Year                         | 2019                        |
| Condition                                 | 1 - Excellent               |
| Expected Useful Life                      | 20 Years                    |
| Remaining Useful Life                     | 18 Years                    |
| Renewal Year                              | 2039                        |
| Quantity / Unit of Measure                | 4 / Each                    |
| Unit Cost                                 | \$500.00                    |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1            |
| Replacement Cost                          | \$3,734.00                  |

## Description

Exterior lighting is primarily provided via wall-mounted LED fixtures. There are incandescent fixtures installed on the north and south elevations.

## Condition Narrative

No major deficiencies were observed or reported, however, the remaining incandescent fixtures should be replaced with LED as a routine maintenance activity.

## Photos



Moberly Lake Fire Hall - D502041



Moberly Lake Fire Hall - D502041

## Recommendations

| Recommendations #1 - Exterior Lighting |                        |
|--|------------------------|
| Type                                   | Life Cycle Replacement |
| Year                                   | 2039                   |
| Cost                                   | \$3,734.00             |

Replace Exterior Lighting

| Element Description                       |  |
|---|--|
| Name                                      | D502053 - Illuminated Combo Exit Signs |
| Installation Year                         | 2010                                   |
| Condition                                 | 2 - Good                               |
| Expected Useful Life                      | 35 Years                               |
| Remaining Useful Life                     | 24 Years                               |
| Renewal Year                              | 2045                                   |
| Quantity / Unit of Measure                | 5 / Each                               |
| Unit Cost                                 | \$450.00                               |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                       |
| Replacement Cost                          | \$4,200.75                             |

### Description

There are wall-mounted combination exit and emergency lighting battery packs installed over exits to direct and illuminate the path of emergency egress. Some units contain emergency lighting only.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D502041

### Recommendations

| Recommendations #1 - Illuminated Combo Exit Signs |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2045                   |
| Cost  | \$4,200.75             |

Replace Illuminated Combo Exit Signs

| Element Description                       |  |
|---|--|
| Name                                      | D503008 - Security Systems - Intrusion Alarm Systems |
| Installation Year                         | 2010   |
| Condition                                 | 2 - Good   |
| Expected Useful Life                      | 20 Years   |
| Remaining Useful Life                     | 9 Years  |
| Renewal Year                              | 2030   |
| Quantity / Unit of Measure                | 410 / SM Building                                    |
| Unit Cost                                 | \$10.00  |
| Difficulty / Regional / Soft Cost Factors | 1.50 / 1.867 / 1                                     |
| Replacement Cost                          | \$11,482.05  |

### Description

There is an intrusion detection system installed that includes keypads, motion sensors, and door contacts. The main controller is located in the mechanical room. The system is manufactured by DSC and is externally monitored. The system also connects to and monitors the hard-wired smoke detectors installed in the Fire Hall.


### Condition Narrative

No major deficiencies were observed or reported. The difficulty factor has been increased to account for the smoke detectors included in the system.

### Photos



Moberly Lake Fire Hall - D503008



Moberly Lake Fire Hall - D503008



Moberly Lake Fire Hall - D503008

## Recommendations

| Recommendations #1 - Security Systems - Intrusion Alarm Systems |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2030                   |
| Cost  | \$11,482.05            |

Replace Security Systems - Intrusion Alarm Systems

| Element Description                       |                                      |
|---|--------------------------------------|
| Name                                      | D503031 - Video Surveillance Systems |
| Installation Year                         | 2015                                 |
| Condition                                 | 2 - Good                             |
| Expected Useful Life                      | 20 Years                             |
| Remaining Useful Life                     | 14 Years                             |
| Renewal Year                              | 2035                                 |
| Quantity / Unit of Measure                | 410 / SM                             |
| Unit Cost                                 | \$10.00                              |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                     |
| Replacement Cost                          | \$7,654.70                           |

### Description

There is a video surveillance system with a camera in the administration area to monitor the exterior generator and fuel tank.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D503031

### Recommendations

| Recommendations #1 - Video Surveillance Systems |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2035                   |
| Cost  | \$7,654.70             |

Replace Video Surveillance Systems



| Element Description                       |   |
|---|---|
| Name                                      | D509002 - Emergency Power Generator Systems |
| Installation Year                         | 2015  |
| Condition                                 | 2 - Good                                    |
| Expected Useful Life                      | 30 Years                                    |
| Remaining Useful Life                     | 24 Years                                    |
| Renewal Year                              | 2045  |
| Quantity / Unit of Measure                | 100 / kVA                                   |
| Unit Cost                                 | \$450.00                                    |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                            |
| Replacement Cost                          | \$84,015.00                                 |

## Description

There is a packaged diesel-fired emergency power generator installed on the south exterior elevation. The generator is manufactured by Kohler Power Systems (Model: 80RE0ZJD). The assembly is rated for 100 kVA and will generate 278 amps at 120/208V.

## Condition Narrative

No major deficiencies were observed or reported.

## Photos



Moberly Lake Fire Hall - D509002



Moberly Lake Fire Hall - D509002



Moberly Lake Fire Hall - D509002



## Recommendations

| Recommendations #1 - Emergency Power Generator Systems |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2045                   |
| Cost   | \$84,015.00            |

Replace Emergency Power Generator Systems

| Element Description                       |   |
|---|---|
| Name                                      | D509031 - Automatic Transfer Switches (ATSs) up to 400A |
| Installation Year                         | 2015  |
| Condition                                 | 2 - Good  |
| Expected Useful Life                      | 40 Years  |
| Remaining Useful Life                     | 34 Years  |
| Renewal Year                              | 2055  |
| Quantity / Unit of Measure                | 1 / Each  |
| Unit Cost                                 | \$7,500.00  |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1  |
| Replacement Cost                          | \$14,002.50   |

### Description

There is an automatic transfer switch installed on the south wall of the 1983 vehicle bay. It is manufactured by Kohler Power Systems.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - D509031

## F Special Construction & Demolition

### F10 Special Construction

| Element Description                       |   |
|---|---|
| Name                                      | F101099 - Other Special Construction - Seacan |
| Installation Year                         | 2012  |
| Condition                                 | 2 - Good                                      |
| Expected Useful Life                      | 30 Years                                      |
| Remaining Useful Life                     | 21 Years                                      |
| Renewal Year                              | 2042  |
| Quantity / Unit of Measure                | 1 / Lump Sum                                  |
| Unit Cost                                 | \$5,000.00                                    |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                              |
| Replacement Cost                          | \$9,335.00                                    |

### Description

There is a packaged shipping container located south of the Fire Hall that is used for general storage.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - F101099



Moberly Lake Fire Hall - F101099

### Recommendations

| Recommendations #1 - Other Special Construction |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2042                   |
| Cost  | \$9,335.00             |

Replace Other Special Construction

## G Building Sitework

### G20 Site Improvements

| Element Description                       |                                   |
|---|-----------------------------------|
| Name                                      | G201005 - Guardrails and Barriers |
| Installation Year                         | 1999                              |
| Condition                                 | 2 - Good                          |
| Expected Useful Life                      | 30 Years                          |
| Remaining Useful Life                     | 8 Years                           |
| Renewal Year                              | 2029                              |
| Quantity / Unit of Measure                | 24 / LM                           |
| Unit Cost                                 | \$1,200.00                        |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                  |
| Replacement Cost                          | \$53,769.60                       |

### Description

There are concrete-filled steel bollards installed on the east and west elevations to guard against vehicle impacts. There are pre-cast concrete jersey barriers installed at the south end of the gravel parking lot and at the north exterior truck fill line.

### Condition Narrative

No major deficiencies were observed or reported. It is recommended to paint the barriers with exterior grade high visibility paint to help with visibility. The cost to paint the barriers is presumed to fall below the cost threshold for repair recommendations (\$5,000) and should be completed as a routine maintenance activity.

### Photos



Moberly Lake Fire Hall - G201005



Moberly Lake Fire Hall - G201005



Moberly Lake Fire Hall - G201005



Moberly Lake Fire Hall - G201005

## Recommendations

| Recommendations #1 - Guardrails and Barriers |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2029                   |
| Cost   | \$53,769.60            |

Replace Guardrails and Barriers



| Element Description                       |  |
|---|--|
| Name                                      | G201025 - Gravel Paved Surface - Roadway |
| Installation Year                         | 2015                                     |
| Condition                                 | 3 - Fair                                 |
| Expected Useful Life                      | 15 Years                                 |
| Remaining Useful Life                     | 9 Years                                  |
| Renewal Year                              | 2030                                     |
| Quantity / Unit of Measure                | 2300 / SM                                |
| Unit Cost                                 | \$35.00                                  |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                         |
| Replacement Cost                          | \$150,293.50                             |

### Description

It is understood that the entire length of gravel surfaced roadway that connects Don Phillips Way to the north, to the asphalt-paved section of Lakeshore Drive to the south, is owned and maintained by the Moberly Lake Fire Hall.

### Condition Narrative

No major deficiencies were observed or reported, however, there are reportedly some grading issues with the roadway. At times of heavy rainfall or snowmelt, water ponds at the west entrance to the fire hall, and reportedly is not contained within the drainage ditch that runs parallel to the roadway. There is some evidence of ground heaving around the west entrance. It is recommended to undertake an engineering study to determine a solution for site ponding/heaving. A recommendation for a study and a placeholder repair have been provided herein.

### Photos




Moberly Lake Fire Hall - G201025



Moberly Lake Fire Hall - G201025



Moberly Lake Fire Hall - G201025



Moberly Lake Fire Hall - G201025

## Recommendations

### Recommendations #1 - Engineering Study - Site Ponding / Heaving

|      |                   |
|------|-------------------|
| Type | Engineering Study |
| Year | 2022              |
| Cost | \$7,500.00        |

Undertake an engineering study to determine the source and provide a solution for site stormwater ponding and ground heaving around the west entrance.

### Recommendations #2 - Placeholder Repair - Site Ponding / Heaving

|      |              |
|------|--------------|
| Type | Major Repair |
| Year | 2023         |
| Cost | \$50,000.00  |

Complete regrading/repairs as directed by the engineering report.

### Recommendations #3 - Gravel Paved Surface - Roadway

|      |                        |
|------|------------------------|
| Type | Life Cycle Replacement |
| Year | 2030                   |
| Cost | \$150,293.50           |

Replace Gravel Paved Surface - Roadway



| Element Description                       |   |
|---|---|
| Name                                      | G202024 - Gravel Paved Surface - Parking Area |
| Installation Year                         | 2000  |
| Condition                                 | 2 - Good                                      |
| Expected Useful Life                      | 15 Years                                      |
| Remaining Useful Life                     | 6 Years                                       |
| Renewal Year                              | 2027  |
| Quantity / Unit of Measure                | 100 / SM                                      |
| Unit Cost                                 | \$25.00                                       |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                              |
| Replacement Cost                          | \$4,667.50                                    |

## Description

There is a gravel-surfaced parking area provided at the east elevation.

## Condition Narrative

No major deficiencies were observed or reported during. The components have surpassed their expected useful life, however, the Remaining Useful Life has been extended to a later year based on the absence of significant deficiencies.

## Photos



Moberly Lake Fire Hall - G202024



Moberly Lake Fire Hall - G202024

## Recommendations

| Recommendations #1 - Gravel Paved Surface - Parking Area |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2027                   |
| Cost   | \$4,667.50             |

Replace Gravel Paved Surface - Parking Area

| Element Description                       |                                   |
|---|-----------------------------------|
| Name                                      | G203022 - Concrete Paved Surfaces |
| Installation Year                         | 2012                              |
| Condition                                 | 2 - Good                          |
| Expected Useful Life                      | 30 Years                          |
| Remaining Useful Life                     | 21 Years                          |
| Renewal Year                              | 2042                              |
| Quantity / Unit of Measure                | 135 / SM                          |
| Unit Cost                                 | \$165.00                          |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                  |
| Replacement Cost                          | \$41,587.43                       |

### Description

There is a cast-in-place concrete pad poured at the west vehicle bay entrance. An additional cast-in-place concrete slab is poured at the south exit below the generator and fuel tank.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - G203022



Moberly Lake Fire Hall - G203022



Moberly Lake Fire Hall - G203022



Moberly Lake Fire Hall - G203022

## Recommendations

| Recommendations #1 - Concrete Paved Surfaces |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2042                   |
| Cost   | \$41,587.43            |

Replace Concrete Paved Surfaces

| Element Description                       |  |
|---|--|
| Name                                      | G204021 - Fencing and Gates - Chain Link Fence |
| Installation Year                         | 2012   |
| Condition                                 | 2 - Good                                       |
| Expected Useful Life                      | 30 Years                                       |
| Remaining Useful Life                     | 21 Years                                       |
| Renewal Year                              | 2042   |
| Quantity / Unit of Measure                | 15 / LM  |
| Unit Cost                                 | \$360.00                                       |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                               |
| Replacement Cost                          | \$10,081.80                                    |

### Description

There is a galvanized metal chain-link fence installed to surround the generator and fuel tank on the south elevation.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - G204021



Moberly Lake Fire Hall - G204021

### Recommendations

| Recommendations #1 - Fencing and Gates - Chain Link Fence |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2042                   |
| Cost  | \$10,081.80            |

Replace Fencing and Gates - Chain Link Fence

## G30 Site Mechanical Utilities

| Element Description                       |                                       |
|---|---------------------------------------|
| Name                                      | G301024 - Water Supply Infrastructure |
| Installation Year                         | 1999                                  |
| Condition                                 | 2 - Good                              |
| Expected Useful Life                      | 50 Years                              |
| Remaining Useful Life                     | 28 Years                              |
| Renewal Year                              | 2049                                  |
| Quantity / Unit of Measure                | 30 / LM                               |
| Unit Cost                                 | \$588.00                              |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                      |
| Replacement Cost                          | \$32,933.88                           |

### Description

A buried water line connects domestic water equipment in the mechanical room to the buried domestic water tank installed south of the Moberly Lake Community Hall.

### Condition Narrative

No major deficiencies were observed or reported.

### Recommendations

| Recommendations #1 - Water Supply Infrastructure |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2049                   |
| Cost   | \$32,933.88            |

Replace Water Supply Infrastructure



| Element Description                       |  |
|---|--|
| Name                                      | G301099 - OtherWater Supply - Buried Water Tanks |
| Installation Year                         | 1999   |
| Condition                                 | 2 - Good   |
| Expected Useful Life                      | 50 Years   |
| Remaining Useful Life                     | 28 Years   |
| Renewal Year                              | 2049   |
| Quantity / Unit of Measure                | 2 / Lump Sum                                     |
| Unit Cost                                 | \$10,000.00                                      |
| Difficulty / Regional / Soft Cost Factors | 2.00 / 1.867 / 1                                 |
| Replacement Cost                          | \$74,680.00                                      |

### Description

It is understood that there are two (2) buried water tanks installed at the site. The first tank is buried north of the Fire Hall and connects to a municipally-owned cistern installed off-property to provide fill-water for fire trucks. The tank includes a fill line at grade level. The second tank is buried south of the Moberly Lake Community Hall and is used for domestic water. Each tank has an estimated size of 10,000 litres. The domestic water tank is used to provide domestic water to the Moberly Lake Community Hall as well as the Fire Hall.

### Condition Narrative

No major deficiencies were observed or reported. The difficulty factor has been adjusted to account for the estimated size of the tanks.

### Photos



Moberly Lake Fire Hall - G301099

### Recommendations

| Recommendations #1 - OtherWater Supply |                        |
|--|------------------------|
| Type                                   | Life Cycle Replacement |
| Year                                   | 2049                   |
| Cost                                   | \$74,680.00            |

Replace OtherWater Supply

| Element Description                       |                                      |
|---|--------------------------------------|
| Name                                      | G302016 - Septic Tank (4000 Gallons) |
| Installation Year                         | 1983                                 |
| Condition                                 | 2 - Good                             |
| Expected Useful Life                      | 50 Years                             |
| Remaining Useful Life                     | 12 Years                             |
| Renewal Year                              | 2033                                 |
| Quantity / Unit of Measure                | 1 / Each                             |
| Unit Cost                                 | \$26,500.00                          |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1                     |
| Replacement Cost                          | \$49,475.50                          |

### Description

There is a buried septic tank that is reportedly located south of the Fire Hall. Technical specifications are not available. Buried sanitary piping connects the tank to the Fire Hall.

### Condition Narrative

The septic tank did not have any reported issues, however, the date it was last emptied is unknown. It is recommended to have the tank emptied as a precaution.

### Recommendations

| Recommendations #1 - Septic Tank (4000 Gallons) |                        |
|---|------------------------|
| Type  | Life Cycle Replacement |
| Year  | 2033                   |
| Cost  | \$49,475.50            |

Replace Septic Tank (4000 Gallons)



| Element Description                       |   |
|---|---|
| Name                                      | G306004 - Fuel Storage Tanks - Aboveground Less than 10,000 L |
| Installation Year                         | 2012  |
| Condition                                 | 2 - Good  |
| Expected Useful Life                      | 30 Years  |
| Remaining Useful Life                     | 21 Years  |
| Renewal Year                              | 2042  |
| Quantity / Unit of Measure                | 1315 / L  |
| Unit Cost                                 | \$30.00   |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1  |
| Replacement Cost                          | \$73,653.15   |

### Description

There is a double-walled diesel fuel tank of steel construction installed on the south elevation. It is manufactured by Westell and has a capacity of 1,315 litres. The tank includes a 1/6 HP fuel pump with a hose and nozzle for truck filling.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - G306004



Moberly Lake Fire Hall - G306004

### Recommendations

| Recommendations #1 - Fuel Storage Tanks - Aboveground Less than 10,000 L |                        |
|--|------------------------|
| Type   | Life Cycle Replacement |
| Year   | 2042                   |
| Cost   | \$73,653.15            |

Replace Fuel Storage Tanks - Aboveground Less than 10,000 L

## G40 Site Electrical Utilities

| Element Description                       |                              |
|---|------------------------------|
| Name                                      | G401011 - Electrical Service |
| Installation Year                         | 1999                         |
| Condition                                 | 2 - Good                     |
| Expected Useful Life                      | 50 Years                     |
| Remaining Useful Life                     | 28 Years                     |
| Renewal Year                              | 2049                         |
| Quantity / Unit of Measure                | 20 / LM                      |
| Unit Cost                                 | \$655.00                     |
| Difficulty / Regional / Soft Cost Factors | 1.00 / 1.867 / 1             |
| Replacement Cost                          | \$24,457.70                  |

### Description

An overhead, single-phase, 120/240V electrical service connects with a meter installed on the building's south elevation from a utility-owned, pole-mounted transformer.

### Condition Narrative

No major deficiencies were observed or reported.

### Photos



Moberly Lake Fire Hall - G401011

### Recommendations

| Recommendations #1 - Electrical Service |                        |
|---|------------------------|
| Type                                    | Life Cycle Replacement |
| Year                                    | 2049                   |
| Cost                                    | \$24,457.70            |

Replace Electrical Service

**Collaborating to Provide Asset Data You Can Trust**

## **APPENDIX B**

### **30-Year Capital Plan Renewal and Repair Summary**

**Project No. 21075**

© Copyright 2021 FCAPX a Division of Roth IAMS Ltd.- All rights reserved



### OPINION OF PROBABLE COST TABLE

|                      |                               |
|----------------------|-------------------------------|
| <b>Client</b>        | Peace River Regional District |
| <b>Site No.</b>      |                               |
| <b>Building Name</b> | Moberly Lake Fire Hall        |
| <b>Address</b>       |                               |
| <b>Project No.</b>   | 21075                         |
| <b>Date</b>          | November 17, 2021             |

| Element Name  | Recommendation Description  | Element Condition | Recommendation Type    | Expected Useful Life (Years) | Recommendation Year | Recommendation Cost | 2021 | 2022     | 2023     | 2024     | 2025 | 2026     | 2027      | 2028     | 2029      | 2030      | 2031 | 2032     | 2033     | 2034     | 2035     | 2036    | 2037 | 2038 | 2039 | 2040      | 2041 | 2042     | 2043 | 2044     | 2045 | 2046 | 2047 | 2048 | 2049     | 2050      | Totals (2021 - 2050) |
|---|---|-------------------|------------------------|------------------------------|---------------------|---------------------|------|----------|----------|----------|------|----------|-----------|----------|-----------|-----------|------|----------|----------|----------|----------|---------|------|------|------|-----------|------|----------|------|----------|------|------|------|------|----------|-----------|----------------------|
| B - Shell   |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| B10 - Substructure  |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| B103001 Structure   | Remove the wood ladder and platform and install an automated winch system for the hose drying tower.  | 3 - Fair          | Major Repair           | 75                           | 2022                | \$10,000            |      | \$10,000 |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$10,000  |                      |
| B20 - Exterior Enclosure  |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| B201010 Exterior Coatings/Paint                                 | Replace Exterior Coatings/Paint   | 4 - Poor          | Life Cycle Replacement | 10                           | 2022                | \$56,010            |      | \$56,010 |          |          |      |          |           |          |           |           |      | \$56,010 |          |          |          |         |      |      |      |           |      | \$56,010 |      |          |      |      |      |      |          |           | \$160,030            |
| B201024 Metal Siding  | Replace Metal Siding  | 2 - Good          | Life Cycle Replacement | 40                           | 2039                | \$224,040           |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      | \$224,040 |      |          |      |          |      |      |      |      |          | \$224,040 |                      |
| B202001 Windows   | Replace Windows   | 2 - Good          | Life Cycle Replacement | 35                           | 2034                | \$12,416            |      |          |          |          |      |          |           |          |           |           |      |          |          | \$12,416 |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$12,416  |                      |
| B203022 Overhead Doors - Industrial                             | Replace Overhead Doors - Industrial   | 2 - Good          | Life Cycle Replacement | 25                           | 2028                | \$67,212            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$67,212  |                      |
| B203023 Single Door - Hollow Metal                              | Replace Single Door - Hollow Metal  | 3 - Fair          | Life Cycle Replacement | 30                           | 2026                | \$23,898            |      |          |          |          |      | \$23,898 |           | \$67,212 |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$23,898  |                      |
| B30 - Roofing   |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| C - Interiors   |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| C101001 Fixed Partitions  | Undertake a hazardous materials assessment  | 2 - Good          | Engineering Study      | 75                           | 2024                | \$5,000             |      |          |          | \$5,000  |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$5,000   |                      |
| C102022 Single Door - Wood                                      | Replace Single Door - Wood  | 2 - Good          | Life Cycle Replacement | 40                           | 2039                | \$33,606            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$33,606  |                      |
| C103000 Cabinets - Kitchens                                     | Replace Cabinets - Kitchens   | 2 - Good          | Life Cycle Replacement | 35                           | 2027                | \$11,202            |      |          |          |          |      |          |           | \$11,202 |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$11,202  |                      |
| C103010 Vanities  | Replace Vanities  | 2 - Good          | Life Cycle Replacement | 25                           | 2027                | \$4,481             |      |          |          |          |      |          |           | \$4,481  |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$4,481   |                      |
| C103011 Cabinets - General                                      | Replace Cabinets - General  | 2 - Good          | Life Cycle Replacement | 35                           | 2034                | \$44,808            |      |          |          |          |      |          |           |          |           |           |      |          |          |          | \$44,808 |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$44,808  |                      |
| C201002 Exterior Stair Construction                             | Replace Exterior Stair Construction   | 2 - Good          | Life Cycle Replacement | 40                           | 2039                | \$18,670            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$18,670  |                      |
| C301005 Paint Wall Covering                                     | Replace Paint Wall Covering   | 2 - Good          | Life Cycle Replacement | 10                           | 2027                | \$11,949            |      |          |          |          |      |          |           | \$11,949 |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$11,949  |                      |
| C301090 Other Wall Finishes - Metal Wall Finish                 | Replace Other Wall Finishes - Metal Wall Finish   | 2 - Good          | Life Cycle Replacement | 30                           | 2029                | \$46,675            |      |          |          |          |      |          |           |          |           | \$46,675  |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$46,675  |                      |
| C302007 Painted / Sealed Concrete Floor                         | Replace Painted / Sealed Concrete Floor   | 2 - Good          | Life Cycle Replacement | 15                           | 2027                | \$19,566            |      |          |          |          |      |          |           | \$19,566 |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$19,566  |                      |
| C302023 Vinyl Sheet Floor                                       | Replace Vinyl Sheet Floor   | 3 - Fair          | Life Cycle Replacement | 15                           | 2034                | \$33,158            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      | \$33,158 |      |      |      |      |          | \$33,158  |                      |
| C303006 Painted Ceiling Structures                              | Replace Painted Ceiling Structures  | 2 - Good          | Life Cycle Replacement | 15                           | 2032                | \$8,962             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$8,962   |                      |
| D - Services  |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| D10 - Conveying   |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| D20 - Plumbing  |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| D201001 Water Closets   | Replace Water Closets   | 2 - Good          | Life Cycle Replacement | 35                           | 2034                | \$3,734             |      |          |          |          |      |          |           |          |           |           |      |          |          |          | \$3,734  |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$3,734   |                      |
| D201003 Lavatories  | Replace Lavatories  | 2 - Good          | Life Cycle Replacement | 35                           | 2034                | \$3,734             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$3,734   |                      |
| D201004 Sinks   | Replace Sinks   | 2 - Good          | Life Cycle Replacement | 35                           | 2034                | \$1,867             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$1,867   |                      |
| D201012 Shower Assembly   | Replace Shower Assembly   | 2 - Good          | Life Cycle Replacement | 25                           | 2027                | \$11,202            |      |          |          |          |      |          |           | \$11,202 |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$11,202  |                      |
| D201016 Custodial Sinks   | Replace Custodial Sinks   | 2 - Good          | Life Cycle Replacement | 30                           | 2029                | \$1,867             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          | \$1,867 |      |      |      |           |      |          |      |          |      |      |      |      |          | \$1,867   |                      |
| D202001 Domestic Water Pipes and Fittings                       | Replace Domestic Water Pipes and Fittings   | 2 - Good          | Life Cycle Replacement | 40                           | 2027                | \$30,619            |      |          |          |          |      |          |           | \$30,619 |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$30,619  |                      |
| D202006 Domestic Water Booster Systems/Pumps                    | Replace Domestic Water Booster Systems/Pumps  | 2 - Good          | Life Cycle Replacement | 20                           | 2037                | \$3,734             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$3,734   |                      |
| D202008 Domestic Water Expansion Tanks/Pressure Tanks           | Replace Domestic Water Expansion Tanks/Pressure Tanks   | 2 - Good          | Life Cycle Replacement | 30                           | 2047                | \$2,987             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$2,987   |                      |
| D202035 Electric Domestic Water Heaters (Residential Tank Type) | Replace Electric Domestic Water Heaters (Residential Tank Type)   | 2 - Good          | Life Cycle Replacement | 12                           | 2029                | \$6,168             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      | \$6,168  |      |      |      |      |          | \$6,168   |                      |
| D203001 Sanitary Waste and Vent Piping                          | Replace Sanitary Waste and Vent Piping  | 2 - Good          | Life Cycle Replacement | 50                           | 2033                | \$34,446            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$34,446  |                      |
| D203007 Interceptor Systems                                     | Replace Interceptor Systems   | 2 - Good          | Life Cycle Replacement | 25                           | 2027                | \$37,340            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           | \$37,340             |
| D30 - HVAC  |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| D301002 Gas Supply Systems                                      | Replace Gas Supply Systems  | 2 - Good          | Life Cycle Replacement | 40                           | 2027                | \$9,339             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           | \$9,339              |
| D302003 Fuel Fired Forced Air Furnace                           | Replace Fuel Fired Forced Air Furnace   | 4 - Poor          | Life Cycle Replacement | 18                           | 2022                | \$4,481             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$4,481   |                      |
| D302032 Fuel-Fired Radiant Tube Heaters                         | Replace Fuel-Fired Radiant Tube Heaters   | 3 - Fair          | Life Cycle Replacement | 18                           | 2024                | \$18,670            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$18,670  |                      |
| D304001 Air Distribution Systems                                | Replace Air Distribution Systems  | 2 - Good          | Life Cycle Replacement | 50                           | 2049                | \$17,923            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$17,923  |                      |
| D304033 Exhaust Fan - Ceiling (Residential)                     | Replace Exhaust Fan - Ceiling (Residential)   | 2 - Good          | Life Cycle Replacement | 25                           | 2028                | \$3,734             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$3,734   |                      |
| D305009 Unit Heaters (Electric)                                 | Replace Unit Heaters (Electric)   | 2 - Good          | Life Cycle Replacement | 18                           | 2027                | \$9,335             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$9,335   |                      |
| D305010 Electric Baseboard Heaters                              | Replace Electric Baseboard Heaters  | 4 - Poor          | Life Cycle Replacement | 18                           | 2022                | \$2,240             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$2,240   |                      |
| D40 - Fire Protection   |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| D403002 Fire Extinguishers                                      | Replace Fire Extinguishers  | 2 - Good          | Life Cycle Replacement | 10                           | 2027                | \$765               |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$765     |                      |
| D50 - Electrical  |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| D501005 Panelboards up to 400A - 1983                           | Replace Panelboards up to 400A - 1983   | 2 - Good          | Life Cycle Replacement | 40                           | 2027                | \$9,335             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$9,335   |                      |
| D501025 LV Main Service Disconnects                             | Replace LV Main Service Disconnects   | 2 - Good          | Life Cycle Replacement | 40                           | 2027                | \$5,601             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$5,601   |                      |
| D502001 Branch Wiring and Devices                               | Replace Branch Wiring and Devices   | 2 - Good          | Life Cycle Replacement | 50                           | 2033                | \$72,720            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$72,720  |                      |
| D502041 Exterior Lighting                                       | Replace Exterior Lighting   | 1 - Excellent     | Life Cycle Replacement | 20                           | 2039                | \$3,734             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$3,734   |                      |
| D502053 Illuminated Combo Exit Signs                            | Replace Illuminated Combo Exit Signs  | 2 - Good          | Life Cycle Replacement | 35                           | 2045                | \$4,201             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$4,201   |                      |
| D503008 Security Systems - Intrusion Alarm Systems              | Replace Security Systems - Intrusion Alarm Systems  | 2 - Good          | Life Cycle Replacement | 20                           | 2030                | \$11,482            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$11,482  |                      |
| D503031 Video Surveillance Systems                              | Replace Video Surveillance Systems  | 2 - Good          | Life Cycle Replacement | 20                           | 2035                | \$7,655             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$7,655   |                      |
| D505002 Emergency Power Generator Systems                       | Replace Emergency Power Generator Systems   | 2 - Good          | Life Cycle Replacement | 30                           | 2045                | \$84,015            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$84,015  |                      |
| E - Equipment & Furnishings                                     |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| F - Special Construction & Demolition                           |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| F101099 Other Special Construction - Seacan                     | Replace Other Special Construction  | 2 - Good          | Life Cycle Replacement | 30                           | 2042                | \$9,335             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$9,335   |                      |
| G - Site Surfacing and Landscaping                              |   |                   |                        |                              |                     |                     |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |
| G201005 Guardrails and Barriers                                 | Replace Guardrails and Barriers   | 2 - Good          | Life Cycle Replacement | 30                           | 2029                | \$53,770            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$53,770  |                      |
| G201025 Gravel Paved Surface - Roadway                          | Underlake an engineering study to determine the source and provide a solution for the stormwater ponding and ground heaving around the west entrance. | 3 - Fair          | Engineering Study      | 15                           | 2022                | \$7,500             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      | \$7,500  |           |                      |
| G201025 Gravel Paved Surface - Roadway                          | Complete grading/repairs as directed by the engineering report.   | 3 - Fair          | Major Repair           | 15                           | 2023                | \$50,000            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$50,000  |                      |
| G201025 Gravel Paved Surface - Roadway                          | Replace Gravel Paved Surface - Roadway  | 3 - Fair          | Life Cycle Replacement | 15                           | 2030                | \$150,294           |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$150,294 |                      |
| G202024 Gravel Paved Surface - Parking Area                     | Replace Gravel Paved Surface - Parking Area   | 2 - Good          | Life Cycle Replacement | 15                           | 2027                | \$4,668             |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$4,668   |                      |
| G203022 Concrete Paved Surfaces                                 | Replace Concrete Paved Surfaces   | 2 - Good          | Life Cycle Replacement | 30                           | 2042                | \$41,587            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$41,587  |                      |
| G204021 Fencing and Gates - Chain Link Fence                    | Replace Fencing and Gates - Chain Link Fence  | 2 - Good          | Life Cycle Replacement | 30                           | 2042                | \$10,082            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$10,082  |                      |
| G301024 Water Supply Infrastructure                             | Replace Water Supply Infrastructure   | 2 - Good          | Life Cycle Replacement | 50                           | 2049                | \$32,934            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$32,934  |                      |
| G301099 Other Water Supply - Buried Water Tanks                 | Replace Other Water Supply  | 2 - Good          | Life Cycle Replacement | 50                           | 2049                | \$74,680            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$74,680  |                      |
| G302016 Septic Tank (4000 Gallons)                              | Replace Septic Tank (4000 Gallons)  | 2 - Good          | Life Cycle Replacement | 50                           | 2033                | \$49,476            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      | \$49,476 |           |                      |
| G304004 Fuel Storage Tanks - Aboveground Less Than 10,000 L     | Replace Fuel Storage Tanks - Aboveground Less Than 10,000 L   | 2 - Good          | Life Cycle Replacement | 30                           | 2042                | \$73,653            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$73,653  |                      |
| G401011 Electrical Service                                      | Replace Electrical Service  | 2 - Good          | Life Cycle Replacement | 50                           | 2049                | \$24,458            |      |          |          |          |      |          |           |          |           |           |      |          |          |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          | \$24,458  |                      |
| Total Capital Renewals  |   |                   |                        |                              |                     | \$1,619,015         | \$0  | \$80,231 | \$50,000 | \$56,828 | \$0  | \$23,898 | \$165,401 | \$70,946 | \$110,480 | \$161,776 | \$0  |          | \$64,972 |          |          |         |      |      |      |           |      |          |      |          |      |      |      |      |          |           |                      |

**APPENDIX C**  
**Reserve Fund Analysis**

| Cash Flow Table                        |                 |                                 |                    |  |                           |   |                 |  |
|--|-----------------|---------------------------------|--------------------|--|---------------------------|---|-----------------|--|
| Scenario 0: No Contribution            |                 |                                 |                    |  |                           |   |                 |  |
| Reserve Fund Opening Balance           |                 | \$                              | 274,135            | Assumed Annual Inflation Rate for Reserve Fund Expenditures      |                           |   |                 | 2.00%                                    |
| Projected Minimum Reserve Fund Balance |                 | \$                              | (2,678,316)        | Assumed Annual Interest Rate for Interest Earned on Reserve Fund |                           |   |                 | 2.00%                                    |
| Year                                   | Opening Balance | Recommended Annual Contribution | Other Contribution | Estimated Inflation Adjusted Expenditures                        | Estimated Interest Earned | % Increase In Recommended Annual Contribution | Closing Balance | Average Contribution Per Unit, Per Month |
| 2021                                   | \$ 274,135      | \$ -                            | \$ -               | \$ -   | \$ 5,483                  | n/a   | \$ 279,618      | \$ -                                     |
| 2022                                   | \$ 279,618      | \$ -                            | \$ -               | \$ 85,680  | \$ 5,538                  | 2.00%   | \$ 199,476      | \$ -                                     |
| 2023                                   | \$ 199,476      | \$ -                            | \$ -               | \$ 54,621  | \$ 4,791                  | 2.00%   | \$ 149,646      | \$ -                                     |
| 2024                                   | \$ 149,646      | \$ -                            | \$ -               | \$ 63,513  | \$ 3,491                  | 2.00%   | \$ 89,623       | \$ -                                     |
| 2025                                   | \$ 89,623       | \$ -                            | \$ -               | \$ -   | \$ 2,393                  | 2.00%   | \$ 92,016       | \$ -                                     |
| 2026                                   | \$ 92,016       | \$ -                            | \$ -               | \$ 27,823  | \$ 1,816                  | 2.00%   | \$ 66,010       | \$ -                                     |
| 2027                                   | \$ 66,010       | \$ -                            | \$ -               | \$ 195,108   | \$ 1,580                  | 2.00%   | \$ (127,518)    | \$ -                                     |
| 2028                                   | \$ (127,518)    | \$ -                            | \$ -               | \$ 85,635  | \$ -                      | 2.00%   | \$ (213,152)    | \$ -                                     |
| 2029                                   | \$ (213,152)    | \$ -                            | \$ -               | \$ 136,557   | \$ -                      | 2.00%   | \$ (349,709)    | \$ -                                     |
| 2030                                   | \$ (349,709)    | \$ -                            | \$ -               | \$ 202,030   | \$ -                      | 2.00%   | \$ (551,739)    | \$ -                                     |
| 2031                                   | \$ (551,739)    | \$ -                            | \$ -               | \$ -   | \$ -                      | 2.00%   | \$ (551,739)    | \$ -                                     |
| 2032                                   | \$ (551,739)    | \$ -                            | \$ -               | \$ 84,860  | \$ -                      | 2.00%   | \$ (636,600)    | \$ -                                     |
| 2033                                   | \$ (636,600)    | \$ -                            | \$ -               | \$ 207,738   | \$ -                      | 2.00%   | \$ (844,338)    | \$ -                                     |
| 2034                                   | \$ (844,338)    | \$ -                            | \$ -               | \$ 91,005  | \$ -                      | 2.00%   | \$ (935,343)    | \$ -                                     |
| 2035                                   | \$ (935,343)    | \$ -                            | \$ -               | \$ 11,084  | \$ -                      | 2.00%   | \$ (946,427)    | \$ -                                     |
| 2036                                   | \$ (946,427)    | \$ -                            | \$ -               | \$ -   | \$ -                      | 2.00%   | \$ (946,427)    | \$ -                                     |
| 2037                                   | \$ (946,427)    | \$ -                            | \$ -               | \$ 36,036  | \$ -                      | 2.00%   | \$ (982,462)    | \$ -                                     |
| 2038                                   | \$ (982,462)    | \$ -                            | \$ -               | \$ 73,513  | \$ -                      | 2.00%   | \$ (1,055,975)  | \$ -                                     |
| 2039                                   | \$ (1,055,975)  | \$ -                            | \$ -               | \$ 470,893   | \$ -                      | 2.00%   | \$ (1,526,868)  | \$ -                                     |
| 2040                                   | \$ (1,526,868)  | \$ -                            | \$ -               | \$ 9,178   | \$ -                      | 2.00%   | \$ (1,536,046)  | \$ -                                     |
| 2041                                   | \$ (1,536,046)  | \$ -                            | \$ -               | \$ 12,482  | \$ -                      | 2.00%   | \$ (1,548,528)  | \$ -                                     |
| 2042                                   | \$ (1,548,528)  | \$ -                            | \$ -               | \$ 373,991   | \$ -                      | 2.00%   | \$ (1,922,518)  | \$ -                                     |
| 2043                                   | \$ (1,922,518)  | \$ -                            | \$ -               | \$ -   | \$ -                      | 2.00%   | \$ (1,922,518)  | \$ -                                     |
| 2044                                   | \$ (1,922,518)  | \$ -                            | \$ -               | \$ -   | \$ -                      | 2.00%   | \$ (1,922,518)  | \$ -                                     |
| 2045                                   | \$ (1,922,518)  | \$ -                            | \$ -               | \$ 417,148   | \$ -                      | 2.00%   | \$ (2,339,666)  | \$ -                                     |
| 2046                                   | \$ (2,339,666)  | \$ -                            | \$ -               | \$ -   | \$ -                      | 2.00%   | \$ (2,339,666)  | \$ -                                     |
| 2047                                   | \$ (2,339,666)  | \$ -                            | \$ -               | \$ 43,927  | \$ -                      | 2.00%   | \$ (2,383,594)  | \$ -                                     |
| 2048                                   | \$ (2,383,594)  | \$ -                            | \$ -               | \$ -   | \$ -                      | 2.00%   | \$ (2,383,594)  | \$ -                                     |
| 2049                                   | \$ (2,383,594)  | \$ -                            | \$ -               | \$ 274,211   | \$ -                      | 2.00%   | \$ (2,657,805)  | \$ -                                     |
| 2050                                   | \$ (2,657,805)  | \$ -                            | \$ -               | \$ 20,511  | \$ -                      | 2.00%   | \$ (2,678,316)  | \$ -                                     |

Note 1: The contributions for the 2021 fiscal year are amounts budgeted by Moberly Lake Fire Hall

Note 2: The 2021 Estimated Inflation Adjusted Expenditures includes approved CRF expenditures for the fiscal year, if any.

Note 3: The projections included in this table are estimates only, based on the information available at the time of preparation. The condition assessment must be updated regularly as the actual figures will vary from the amounts detailed in this table due to changes in interest rates, inflation rates and scheduling of the repair/replacement work.





| <b>Cash Flow Table</b>                                   |                 |                                 |                    |  |                           |   |                 |  |
|--|-----------------|---------------------------------|--------------------|--|---------------------------|---|-----------------|--|
| <b>Scenario 1: Contributions Increase with Inflation</b> |                 |                                 |                    |  |                           |   |                 |  |
| Reserve Fund Opening Balance                             |                 | \$                              | 274,135            | Assumed Annual Inflation Rate for Reserve Fund Expenditures      |                           |   |                 | 2.00%                                    |
| Projected Minimum Reserve Fund Balance                   |                 | \$                              | 21,944             | Assumed Annual Interest Rate for Interest Earned on Reserve Fund |                           |   |                 | 2.00%                                    |
| Year   | Opening Balance | Recommended Annual Contribution | Other Contribution | Estimated Inflation Adjusted Expenditures                        | Estimated Interest Earned | % Increase In Recommended Annual Contribution | Closing Balance | Average Contribution Per Unit, Per Month |
| 2021   | \$ 274,135      | \$ -                            | \$ -               | \$ -   | \$ 5,483                  | n/a   | \$ 279,618      | \$ -                                     |
| 2022   | \$ 279,618      | \$ 73,500                       | \$ -               | \$ 85,680  | \$ 5,538                  | 2.00%   | \$ 272,976      | \$ 6,125                                 |
| 2023   | \$ 272,976      | \$ 74,970                       | \$ -               | \$ 54,621  | \$ 5,526                  | 2.00%   | \$ 298,851      | \$ 6,248                                 |
| 2024   | \$ 298,851      | \$ 76,469                       | \$ -               | \$ 63,513  | \$ 5,718                  | 2.00%   | \$ 317,525      | \$ 6,372                                 |
| 2025   | \$ 317,525      | \$ 77,999                       | \$ -               | \$ -   | \$ 6,164                  | 2.00%   | \$ 401,687      | \$ 6,500                                 |
| 2026   | \$ 401,687      | \$ 79,559                       | \$ -               | \$ 27,823  | \$ 7,192                  | 2.00%   | \$ 460,616      | \$ 6,630                                 |
| 2027   | \$ 460,616      | \$ 81,150                       | \$ -               | \$ 195,108   | \$ 8,623                  | 2.00%   | \$ 355,281      | \$ 6,762                                 |
| 2028   | \$ 355,281      | \$ 82,773                       | \$ -               | \$ 85,635  | \$ 8,159                  | 2.00%   | \$ 360,578      | \$ 6,898                                 |
| 2029   | \$ 360,578      | \$ 84,428                       | \$ -               | \$ 136,557   | \$ 7,159                  | 2.00%   | \$ 315,608      | \$ 7,036                                 |
| 2030   | \$ 315,608      | \$ 86,117                       | \$ -               | \$ 202,030   | \$ 6,762                  | 2.00%   | \$ 206,457      | \$ 7,176                                 |
| 2031   | \$ 206,457      | \$ 87,839                       | \$ -               | \$ -   | \$ 5,221                  | 2.00%   | \$ 299,517      | \$ 7,320                                 |
| 2032   | \$ 299,517      | \$ 89,596                       | \$ -               | \$ 84,860  | \$ 5,060                  | 2.00%   | \$ 309,312      | \$ 7,466                                 |
| 2033   | \$ 309,312      | \$ 91,388                       | \$ -               | \$ 207,738   | \$ 6,088                  | 2.00%   | \$ 199,051      | \$ 7,616                                 |
| 2034   | \$ 199,051      | \$ 93,216                       | \$ -               | \$ 91,005  | \$ 5,084                  | 2.00%   | \$ 206,345      | \$ 7,768                                 |
| 2035   | \$ 206,345      | \$ 95,080                       | \$ -               | \$ 11,084  | \$ 4,054                  | 2.00%   | \$ 294,395      | \$ 7,923                                 |
| 2036   | \$ 294,395      | \$ 96,982                       | \$ -               | \$ -   | \$ 5,007                  | 2.00%   | \$ 396,384      | \$ 8,082                                 |
| 2037   | \$ 396,384      | \$ 98,921                       | \$ -               | \$ 36,036  | \$ 6,908                  | 2.00%   | \$ 466,178      | \$ 8,243                                 |
| 2038   | \$ 466,178      | \$ 100,900                      | \$ -               | \$ 73,513  | \$ 8,626                  | 2.00%   | \$ 502,190      | \$ 8,408                                 |
| 2039   | \$ 502,190      | \$ 102,918                      | \$ -               | \$ 470,893   | \$ 9,684                  | 2.00%   | \$ 143,899      | \$ 8,576                                 |
| 2040   | \$ 143,899      | \$ 104,976                      | \$ -               | \$ 9,178   | \$ 6,461                  | 2.00%   | \$ 246,158      | \$ 8,748                                 |
| 2041   | \$ 246,158      | \$ 107,076                      | \$ -               | \$ 12,482  | \$ 3,901                  | 2.00%   | \$ 344,652      | \$ 8,923                                 |
| 2042   | \$ 344,652      | \$ 109,217                      | \$ -               | \$ 373,991   | \$ 5,908                  | 2.00%   | \$ 85,787       | \$ 9,101                                 |
| 2043   | \$ 85,787       | \$ 111,401                      | \$ -               | \$ -   | \$ 4,304                  | 2.00%   | \$ 201,493      | \$ 9,283                                 |
| 2044   | \$ 201,493      | \$ 113,630                      | \$ -               | \$ -   | \$ 2,873                  | 2.00%   | \$ 317,995      | \$ 9,469                                 |
| 2045   | \$ 317,995      | \$ 115,902                      | \$ -               | \$ 417,148   | \$ 5,195                  | 2.00%   | \$ 21,944       | \$ 9,659                                 |
| 2046   | \$ 21,944       | \$ 118,220                      | \$ -               | \$ -   | \$ 3,399                  | 2.00%   | \$ 143,563      | \$ 9,852                                 |
| 2047   | \$ 143,563      | \$ 120,585                      | \$ -               | \$ 43,927  | \$ 1,655                  | 2.00%   | \$ 221,876      | \$ 10,049                                |
| 2048   | \$ 221,876      | \$ 122,996                      | \$ -               | \$ -   | \$ 3,654                  | 2.00%   | \$ 348,526      | \$ 10,250                                |
| 2049   | \$ 348,526      | \$ 125,456                      | \$ -               | \$ 274,211   | \$ 5,704                  | 2.00%   | \$ 205,475      | \$ 10,455                                |
| 2050   | \$ 205,475      | \$ 127,965                      | \$ -               | \$ 20,511  | \$ 5,540                  | 2.00%   | \$ 318,470      | \$ 10,664                                |

Note 1: The contributions for the 2021 fiscal year are amounts budgeted by Moberly Lake Fire Hall


Note 2: The 2021 Estimated Inflation Adjusted Expenditures includes approved CRF expenditures for the fiscal year, if any.

Note 3: The projections included in this table are estimates only, based on the information available at the time of preparation. The condition assessment must be updated regularly as the actual figures will vary from the amounts detailed in this table due to changes in interest rates, inflation rates and scheduling of the repair/replacement work.

# F·CAP·X

**APPENDIX D**  
**Floor Plan/Site Plan**





**APPENDIX E**  
**Preventative Maintenance Plan**

## Moberly Lake Fire Hall

### Equipment List

| Uniformat Code | Uniformat Name  | Quantity      | Description (If Applicable) | PM ID Number |
|----------------|---|---------------|-----------------------------|--------------|
| B203022        | Overhead Doors - Industrial                             | 3             |                             | 0003         |
| D202006        | Domestic Water Booster Systems/Pumps                    | 1             |                             | 0016         |
| D202008        | Domestic Water Expansion Tanks/Pressure Tank            | 1             | Well Water Pressure Tank    | 0017         |
| D202035        | Electric Domestic Water Heaters (Residential Tank Type) | 1             |                             | 0023         |
| D302003        | Fuel Fired Forced Air Furnace                           | 1             |                             | 0030         |
| D302032        | Fuel-Fired Radiant Tube Heaters                         | 2             |                             | 0031         |
| D305009        | Unit Heaters (Electric)                                 | 2             |                             | 0058         |
| D403002        | Fire Extinguishers                                      | Not Available |                             | 0071         |
| D501005        | Panelboards up to 400A                                  | 2             |                             | 0077         |
| D501025        | LV Main Service Disconnects                             | 1             |                             | 0079         |
| D509002        | Emergency Power Generator Systems                       | 1             |                             | 0085         |
| D503008        | Illuminated Combo Exit Signs                            | Not Available |                             | 0086         |
| D509031        | Automatic Transfer Switches (ATSS) up to 400A           | 1             |                             | 0088         |
| G306004        | Fuel Storage Tanks - Aboveground Less than 10,000 L     | 1             |                             | 0092         |



**Moberly Lake Fire Hall**  
**Preventative Maintenance Plan**

| PM ID Number | Component Name                                | PM Task List   | Frequency     | Estimated Time (Minutes) | Quantity | Resource/Craft      | Materials / Consumables                                       | LOTO (Y/N) |
|--------------|---|--|---------------|--------------------------|----------|---------------------|---|------------|
| 0003         | Overhead Doors - Industrial                   | Clean all hinges/hardware and lubricate as required per the manufacture's specifications.<br>Inspect and clean all rollers, bearings, cables, chains, shaft, tracks, and hardware.<br>Clean and test automatic sensors/door operators.<br>Test operation of all buttons, controls, and switches.<br>Inspect the motor, including electrical connections.<br>Check electric motors for excessive vibration, unusual noise, and odours.<br>Lubricate the motor as per manufacturer's specifications.<br>Tighten the sprockets, brake solenoids, and armatures, as required.<br>Lubricate all bearings, chains, gear reducers, disconnects and pivot points as per the manufacturer's specifications,<br>Inspect the operator bearings, disconnect linkage, and chain hoist assemblies (If Applicable).<br>Test the emergency shut-off switch, if present.<br>Verify the sequence of operation, including any controls and safety mechanisms.                     | quarterly     | 120                      | Each     | Door Technician     | Toolset, Lubricant, Testing Equipment                         | Y          |
| 0016         | Pumps   | Visually assess the pump, fittings, and mounts for signs of corrosion, excessive sweating, and leaks.<br>Lubricate pump bearings as per manufacturer's specifications<br>Lubricate motor bearing as per manufacturer's specifications<br>Check motor mounts and vibration pads to ensure there is not excessive vibration (If applicable).<br>Ensure vents are clear of dust and obstruction.<br>Visually assess electrical connections for loose or frayed wiring.<br>Visually assess all mechanical seals.<br>Verify the sequence of operation, including any controls, redundancy systems, and safety mechanisms.   | weekly        | 10                       | Each     | Building Technician | Toolset   | N          |
| 0017         | Domestic Water Expansion Tanks/Pressure Tank, | Visually assess the tank and associated fittings for signs of corrosion or leaks.<br>Check and record any associated pressure gauges and compare with past data.<br>If there is a drop in pressure, or domestic water pressure is low, test the pressure of the tank and add/remove air as required.<br>If possible, listen for unusual sounds that may indicate a perforation in the interior bladder (if applicable) such as bubbling or dripping.   | weekly        | 5                        | Each     | Building Technician | NA  | N          |
| 0023         | Electric Domestic Water Heaters               | Inspect the tank and associated pipes and fittings for signs of leaks or corrosion.<br>Visually assess electrical connections for loose or frayed wiring.<br>Flush the tank. To prevent a vacuum from forming during flushing, run the hot water in a nearby sink and leave it running for the duration of the flushing process. Connect a hose or transfer pump to the drain outlet of the hot water heater and open the drain/blow down valve. Leave the valve open until water runs clear and free of sediment. Close the drain valve and turn off the hot water in the nearby tap set.   | semi-annually | 20                       | Each     | Building Technician | Toolset, Drain Hose/Transfer Pump                             | N          |
| 0030         | Fuel Fired Forced Air Furnace                 | Replace filters, if needed.<br>Depower the furnace and remove the front cover(s). Remove any dirt and debris from the cabinet interior.<br>Check the interior components for signs of excessive wear and tear, indications of burn marks or short circuits, and oxidization.<br>Check the burner element for signs of material breakdown or blockages.<br>Inspect the blower motor for sings of damage or excessive wear and tear.<br>Visually assess electrical connections for loose or frayed wiring.<br>Check to ensure the condensate drain line is free of clogs or blockages and is properly directed to a sanitary drain. (If applicable)<br>Check to ensure the vent/chimney is free of blockages.<br>Inspect the chimney to ensure it is free of rust, moisture, or leaks.<br>Inspect gas/fuel piping to ensure it is free of rust or leaks.<br>Verify the sequence of operation, including any controls, redundancy systems, and safety mechanisms. | quarterly     | 20                       | Each     | Building Technician | Toolset, Filters, Cleaning Supplies                           | Y          |
| 0030         | Fuel Fired Forced Air Furnace                 | Replace filters.<br>Replace the fan belt (If applicable).<br>Remove the front cover(s) and inspect and test all system components including but not limited to; gas/fuel-fired burners, ignition systems, pilot light systems, burner assemblies, blower motor, dampers, and chimneys.<br>Tighten all mechanical and electrical components.<br>Verify the sequence of operation, including any controls, redundancy systems, and safety mechanisms.  | semi-annually | 45                       | Each     | HVAC Technician     | Toolset, Filters, Belts, Testing Equipment                    | Y          |
| 0031         | Fuel Fired Radiant Tube Heaters               | Clean heating elements with a non-abrasive cleaner that is approved by the manufacturer. Compressed air may be used to clear out dust and debris.<br>Inspect radiant heating elements for signs of cracks, damage, deterioration, or leaks.<br>Remove the cover(s) and inspect and test all system components including but not limited to; gas/fuel-fired burners, ignition systems, pilot light systems, burner assemblies, dampers, and chimneys.<br>Tighten all mechanical and electrical components.<br>Verify the sequence of operation, including any controls, redundancy systems, and safety mechanisms.  | semi-annually | 120                      | Each     | Gas Technician      | Toolset, Testing Equipment, Cleaning Supplies, Air Compressor | Y          |

**Moberly Lake Fire Hall**  
**Preventative Maintenance Plan**

| PM ID Number | Component Name                    | PM Task List  | Frequency | Estimated Time (Minutes) | Quantity | Resource/Craft      | Materials / Consumables            | LOTO (Y/N) |
|--------------|-----------------------------------|---|-----------|--------------------------|----------|---------------------|------------------------------------|------------|
| 0058         | Unit Heaters (Electric)           | Depower the unit and open the cabinet and clean the interior, including fan blades if they are accessible.  | quarterly | 20                       | Each     | Building Technician | Toolset, Cleaning Supplies         | Y          |
|              |                                   | While the unit is off, inspect the interior components for signs of damage, burns, or unusual odours.   |           |                          |          |                     |                                    |            |
|              |                                   | Ensure fan bearings are lubricated as per manufacturer specification.   |           |                          |          |                     |                                    |            |
|              |                                   | Visually assess electrical connections and heating element for loose or frayed wiring.  |           |                          |          |                     |                                    |            |
|              |                                   | Clean any fins or manifolds.  |           |                          |          |                     |                                    |            |
|              |                                   | Close the cabinet and restore power to the unit.  |           |                          |          |                     |                                    |            |
|              |                                   | Inspect the unit under normal operation and monitor for unusual noises, odours, or excessive vibration.   |           |                          |          |                     |                                    |            |
|              |                                   | Verify the sequence of operation, including any controls, redundancy systems, and safety mechanisms.  |           |                          |          |                     |                                    |            |
| 0071         | Fire Extinguishers                | Inspect the fire extinguisher and ensure the needle reads within acceptable ranges on the pressure gauge. Ensure the fire extinguisher is properly mounted/seated.                | monthly   | 5                        | Each     | Building Technician | NA                                 | N          |
|              |                                   | Check to ensure pins are in place and secured with unbroken break-away ties.  |           |                          |          |                     |                                    |            |
|              |                                   | Initial the monthly inspection tags.  |           |                          |          |                     |                                    |            |
| 0071         | Fire Extinguishers                | Complete an annual inspection in accordance with fire code regulations and update inspection tags. Annual inspections must be performed by a technician who is licensed to do so. | annually  | 10                       | Each     | Licensed Technician | Inspection Tags                    | N          |
| 0071         | Fire Extinguishers                | Complete hydrostatic testing. Recharge or replace the fire extinguisher as needed.  | 10 years  | 30                       | Each     | Licensed Technician | Specialized re-charging equipment. | N          |
| 0077         | Panelboards                       | Perform thermal imaging (infrared scanning) to detect hot spots (excess heat) in electrical components.   | 3 years   | 10                       | Each     | Electrician         | Thermal Imaging Camera, Toolset    | N          |
|              |                                   | While thermal imaging is being undertaken, inspect electrical panelboards for missing breakers, panel schedules, knockouts, or unusual sounds or odours.                          |           |                          |          |                     |                                    |            |
|              |                                   | Provide a detailed thermal imaging report based on the results of the infrared scanning.  |           |                          |          |                     |                                    |            |
| 0079         | Main Switches / Disconnects       | Perform thermal imaging (infrared scanning) to detect hot spots (excess heat) in electrical components.   | 3 years   | 10                       | Each     | Electrician         | Thermal Imaging Camera, Toolset    | N          |
|              |                                   | While thermal imaging is being undertaken, inspect the switch for missing schedules, knockouts, or unusual sounds or odours.  |           |                          |          |                     |                                    |            |
|              |                                   | Provide a detailed thermal imaging report based on the results of the infrared scanning.  |           |                          |          |                     |                                    |            |
| 0085         | Emergency Power Generator Systems | Inspect fuel level and pressure to ensure it is full.   | weekly    | 45                       | Each     | Building Technician | Hearing Protection                 | N          |
|              |                                   | Inspect lubricating oil and engine coolant levels and report if they not compliant with manufacturer specifications.  |           |                          |          |                     |                                    |            |
|              |                                   | Test annunciator lamps to confirm that they are operational, if applicable.   |           |                          |          |                     |                                    |            |
|              |                                   | If the unit has a display, check it to ensure there are no alarms or notifications.   |           |                          |          |                     |                                    |            |
|              |                                   | Visually assess the entire system for signs of damage, leaks, corrosion, or other issues.   |           |                          |          |                     |                                    |            |
|              |                                   | Operate the generator for 30 minutes, not under electrical load. (No Load Test)   |           |                          |          |                     |                                    |            |
|              |                                   | Inspect the unit while it is running and monitor for unusual noises, odours, or excessive vibration.  |           |                          |          |                     |                                    |            |
|              |                                   | Record any available statistics while the generator is operable and compare to past collected data.   |           |                          |          |                     |                                    |            |
| 0085         | Emergency Power Generator Systems | Inspect for correct operation of all auxiliary equipment, e.g., radiator shutter control, coolant pumps, fuel transfer pumps, oil coolers, and engine room ventilation system(s). | monthly   | 75                       | Each     | Building Technician | Hearing Protection                 | N          |
|              |                                   | Note: This monthly preventative maintenance event should replace the weekly preventative maintenance event that would normally fall on this week.                                 |           |                          |          |                     |                                    |            |
|              |                                   | Inspect day tank fuel level and pressure to ensure it is full.  |           |                          |          |                     |                                    |            |
|              |                                   | Inspect lubricating oil and engine coolant levels and report if they not compliant with manufacturer specifications.  |           |                          |          |                     |                                    |            |
|              |                                   | Test annunciator lamps to confirm that they are operational, if applicable.   |           |                          |          |                     |                                    |            |
|              |                                   | If the unit has a display, check it to ensure there are no alarms or notifications.   |           |                          |          |                     |                                    |            |
|              |                                   | Visually assess the entire system for signs of damage, leaks, corrosion, or other issues.   |           |                          |          |                     |                                    |            |
|              |                                   | Operate the generator for 60 minutes under electrical load. (Full Load Test)  |           |                          |          |                     |                                    |            |
|              |                                   | Inspect the unit while it is running and monitor for unusual noises, odours, or excessive vibration.  |           |                          |          |                     |                                    |            |
|              |                                   | Record any available statistics while the generator is operable and compare to past collected data.   |           |                          |          |                     |                                    |            |
|              |                                   | While the full load test is being completed, ensure any lighting operated by the generator for use as emergency lighting is illuminated properly.                                 |           |                          |          |                     |                                    |            |
|              |                                   | Inspect for correct operation of all auxiliary equipment, e.g., radiator shutter control, coolant pumps, fuel transfer pumps, oil coolers, and engine room ventilation system(s). |           |                          |          |                     |                                    |            |

**Moberly Lake Fire Hall**  
**Preventative Maintenance Plan**

| PM ID Number | Component Name  | PM Task List   | Frequency     | Estimated Time (Minutes) | Quantity | Resource/Craft                | Materials / Consumables   | LOTO (Y/N) |
|--------------|---|--|---------------|--------------------------|----------|-------------------------------|---|------------|
| 0085         | Emergency Power Generator Systems   | Inspect, test, and calibrate all generator systems including but not limited to; the engine and all associated components, fuel tanks, fuel pumps, filters, oil, coolant, controls, transfer switches, dampers/linkages, safety systems.<br>Clean all generator systems with a manufacturer approved degreasing agent or non-abrasive cleaner.<br>Lubricate any bearings/nipples as per manufacturer specifications.<br>Replace any oil/coolant filters<br>Test the voltage of the batteries and replace if they are outputting less than 80% of the rated voltage.<br>Inspect, test, and calibrate the battery charging station.<br>Check belt alignment and correct as needed. Replace the belts, if needed.<br>Test operation of any manual or automatic transfer switching equipment.<br>Operate the generator for 60 minutes, under full electrical load. (Full Load Test)<br>Record any available statistics while the generator is operable and compare to past collected data.   | semi-annually | 180                      | Each     | Licensed Generator Technician | Hearing Protection, Toolset, Lubricant, Belts, Coolant, Cleaning Supplies | Y          |
| 0085         | Emergency Power Generator Systems   | Inspect, test, and calibrate all generator systems including but not limited to; the engine and all associated components, fuel tanks, fuel pumps, filters, oil, coolant, controls, transfer switches, dampers/linkages, safety systems.<br>Clean all generator systems with a manufacturer approved degreasing agent or non-abrasive cleaner.<br>Lubricate any bearings/nipples as per manufacturer specifications.<br>Clean and lubricate all linkages/dampers.<br>Test the voltage of the batteries and replace if they are outputting less than 80% of the rated voltage.<br>Inspect, test, and calibrate the battery charging station.<br>Check belt alignment and correct as needed. Replace the belts, if needed.<br>Test operation of any manual or automatic transfer switching equipment.<br>Test strength of coolant and chemical protection level of coolant inhibitors.<br>Inspect the exhaust system. Check and record the back pressure of the exhaust system to ensure that it complies with the engine manufacturer's requirements, and compare with previous readings.<br>Test surge suppressor and rotating rectifier on brushless machines.<br>Clean rotor and stator windings using clean compressed air.<br>Inspect coupling bolts and alignment.<br>For spark ignition engines, inspect all components of ignition system(s) and service or replace as appropriate.<br>Inspect all external surfaces of heat exchanger(s) and clean as necessary.<br>Operate the generator for 120 minutes, under full electrical load. (Full Load Test)<br>Record any available statistics while the generator is operable and compare to past collected data. | annually      | 240                      | Each     | Licensed Generator Technician | Hearing Protection, Toolset, Lubricant, Belts, Coolant, Cleaning Supplies | Y          |
| 0086         | Emergency Lighting - Battery Pack Units (EBUs), Emergency Lighting Systems, Illuminated Combo | Check to confirm operation of light(s) and that unit is secure and free from obstruction. Confirm operation of light by engaging test switch (Battery Operated Devices) or otherwise depowering the unit. Lights must remain illuminated for 30 minutes.<br>Initial the monthly inspection tags.   | monthly       | 60                       | Total    | Building Technician           | NA  | N          |
| 0086         | Emergency Lighting - Battery Pack Units (EBUs), Emergency Lighting Systems,                   | Annual certification of the emergency lighting system including a full timed test for each light (90 minutes). Annual certification must be completed by a technician who is licensed to do so.<br>Provide annual inspection tags on each unit.  | annually      | 180                      | Total    | Licensed Technician           | Toolset, Testing Equipment  | N          |
| 0088         | Automatic Transfer Switches (ATSs) up to 400A   | Note that transfer switch operation is included under the emergency generator task list and this task list is specific to the electrical components of the transfer switch.<br>Perform thermal imaging (infrared scanning) to detect hot spots (excess heat) in electrical components.<br>While thermal imaging is being undertaken, inspect the transfer switch for missing knockouts, or unusual sounds or odours.<br>Provide a detailed thermal imaging report based on the results of the infrared scanning.   | 3 years       | 10                       | Each     | Electrician                   | Thermal Imaging Camera, Toolset   | Y          |
| 0092         | Fuel Storage Tanks - Aboveground Less than 10,000 L   | Ensure the pathway to the tank is clear of obstruction.<br>Remove vegetation growth around the tank and cement pad (if applicable).<br>Check for leaks, spills, or unusual odours.<br>Wipe the tank exterior with a damp rag to removed build-up of grime.<br>Visually assess the tank fill or regulator components.<br>Ensure the fill cap is secured and locked (if applicable).   | weekly        | 10                       | Each     | Building Technician           | NA  | N          |