

METHODOLOGY - BCA 30 Year Evaluation period ► Focus on first 5-6 years (2021-2026) Cost threshold \$5,000 ► Capital costs included ▶ Maintenance/minor repairs mentioned but costs excluded ► Class D Cost Estimates (+/- 40%) Expected Useful Life (EUL) ▶ Theoretical Not required replacement A component that is past its theoretical EUL is evaluated on: ► Expert opinion, will it last 5 years. Recommendation Study ► Major Repair ▶ Lifecycle Replacement Integrated Asset Management Strategies

BUILDING CONDITION ASSESSMENT

- Includes
 - ▶ Current Condition of the Component vs. Expected Useful Life
 - ► Capital Renewal Cost
 - ► Focus on Individual Component
- Excludes:
 - Operational Issues
 - ▶ Building Usage
 - Functional Assessment





ASSESSMENT - RUL


A component that is past its theoretical expected useful life (EUL) or will reach its EUL before 2027 is evaluate in the following way:

- No major deficiencies, still functioning as intended, based on assessor expert opinion will remain in good condition until the next visual assessment – Replacement is set at 2027.
- Minor deficiencies, fair condition, still functional, based on assessor expert opinion it will not function until next assessment – Replacement is set in the short-term
- > Failed, not functional, needs major repairs Replacement is immediate









MAINTENANCE VS. CAPITAL RENEWAL

- Maintenance Item
 - ► Cost is less that \$5,000
 - ► Requires repair to a small portion of the component and not a full replacement
 - ▶ Requires labour only, no costs associated with the repair
- Capital Renewal
 - ▶ Cost for full replacement of the component is greater than \$5,000
 - ▶ Full replacement of the component





FACILITY CONDITION INDEX (FCI)

- ▶ The Facility Condition Index (FCI) gives an indication of a building overall condition.
- ▶ The value is based on a 0-100%+ scale and is derived by dividing the repair costs for a facility by a Current Replacement Value (CRV). The FCI is calculated using only the current condition values, not taking into account the future needs identified in the life cycle evaluation.
- Site items (GXXXX) are removed from this calculation as the focus is on the building itself
- ▶ No site features or soft costs associated with construction included in the calculation

5-Year FCI = <u>Sum of 5-Year Renewal Need for the Building</u> x 100 Current Replacement Value of the Building

0 to 10% - Good 11 to 20% - Fair 21-50% - Poor Greater than 50% - Prohibitive to Repair






CACHE CREEK COMMUNITY HALL




Immediate Items (2021):


- Remove natural gas connection maintenance
- Replace Fire Extinguisher (\$569)
- Replace Outdoor Rink dasher boards (\$100,818)
- Replace outdoor wood bleachers (\$29,872)
 Replace playground equipment to restore safe functionality
- Replace and move outhouses (\$18,670)
- Replace site electrical and pole light fixtures (\$38,647)

- Study to determine integrity of foundation and structure and associated repairs (\$10,000)
- Replace exterior metal grilles (\$1,494)
- Replace exterior wood soffits and re-paint (\$13,367)
- Replace single-pane windows and exterior wood doors (\$29,592)
- Replace roofing (\$9,708)
- Replace deteriorated concrete walkways (\$6,161)





GOLATA CREEK COMMUNITY HALL Capital Needs by Year Based on Uniformat \$250,000 \$200,000 \$150,000 \$100,000 Immediate Items (2021): - Replace non-functioning domestic water pump for well Replace non-functioning domestic water heater \$50,000 2022: - Engineering Study on concealed partitions Hazardous Materials Assessment 2022 2023 2024 2026 ■A - Substructure ■B - Shell C - Interiors ■ E - Equipment & Furnishings ■F - Special Construction & Demolition ■D - Services ■G - Sitework



JACKFISH COMMUNITY HALL



Immediate Items (2021):


- Engineering study to design exhaust system for commercial kitchen
- Install fire suppression system for kitchen hood (Code)


2022:

- Replace vinyl tile and 1987 vinyl sheet flooring

Integrated Asset Management Strategies

- Install kitchen exhaust
- Replace exterior wood ramp and concrete landing
- Replace wood fencing
- Replace deteriorated wood framing at shed and install a means of locking/security for the storage room





MOBERLY LAKE COMMUNITY HALL




Immediate Items (2021):

- Replace fire extinguishers and update inspection tags

2022:

- Replace wood wall finish
- Replace 1991 vinyl sheet flooring in the Main Hall
- Replace acoustic tile ceiling in the Main Hall



MOBERLY LAKE COMMUNITY HALL

Uniformat Division	Immediate 2021	Short Term 2022-2026	Mid Term 2027-2031	Long Term 2032-2050	Totals
A-Substructure	\$ -	\$ -	Ş -	\$ -	\$ -
B- Shell	\$ -	\$ -	\$ 35,706	\$ 46,955	\$ 82,661
C - Interiors	\$ -	\$ 98,709	\$ 30,937	\$ 164,332	\$ 293,978
D - Services	\$ 2,520	\$ 31,272	\$ 17,083	\$ 136,329	\$ 187,204
E - Equipment & Furnishings	\$ -	\$ -	\$ -	\$ -	\$ -
F - Special Construction	\$ -	\$ -	\$ -	\$ -	\$ -
G - Building Sitework	\$ -	\$ 47,842	\$ -	\$ 89,289	\$ 137,131
Totals	\$ 2,520	\$ 177,823	\$ 83,726	\$ 436,905	\$ 700,975

Constructed: 1991 Additions: 2003 5-Year FCI = \$\frac{\$132,500}{\$1,187,200} x 100

5-Year FCI = 11.2% (Fair)





UPPER HALFWAY COMMUNITY HALL





Immediate Items (2021):

- Install a fire extinguisher (Code)


2022:


- Replace wood wall/ceiling finish
- Replace laminate wood floors
- Replace exterior lighting
- Regrade gravel parking area






NORTH PEACE FAIRGROUNDS **Adeline Kelly Exhibit** Constructed: 2014 Capital Needs by Year Based on Uniformat \$6,000 \$5,000 \$4,000 \$3,000 2027-2031 \$2,000 Ş -\$1,000 S -S-S -\$ 54,516 \$ 54,516 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 C - Interiors \$ 5,937 \$ 28,509 \$ 34,446 \$ -\$ -\$ -\$ 21,545 ■A - Substructure ■C - Interiors ■D - Services ■F - Special Construction & Demolition \$ -\$ -\$ -\$ -\$ -■E - Equipment & Furnishings ■G - Sitework \$ -\$ -\$ -\$ -\$ -\$ -\$ 4,854 \$ 4,854 \$ 5,937 \$ -\$ 109,425 \$ 115,362








CHARLIE LAKE FIRE HALL




Immediate Items (2021):

- Engineering study to review condition of structure between original building and addition and conduct recommended repairs
- Replace rusted and worn domestic water heater Engineering study of grading around the building perimeter and conduct associated repairs.


- Repairs to concrete slab-on-grade to correct uneven surfaces
- Move domestic water piping away from electrical outlets Engineering study of heating water distribution and glycol loop and
- conduct associated repairs





Energy Audit – Energy Conservation Methods

- Lighting retrofit to LED
- Install a high efficiency domestic water heater
- Reduce temperature setting for the building at night







MOBERLY LAKE FIRE HALL Capital Needs by Year Based on Uniformat \$350,000 \$300,000 \$250,000 \$200,000 \$150,000 \$100,000 2022: - Repaint exterior metal cladding Install automated winch system for access to hose tower, \$50,000 current system is unsafe - Replace forced-air furnace - Engineering study for to assess ponding and heaving of gravel roadway and conduct recommended repairs 2021 2024 Year A - Substructure ■B - Shell C - Interiors ■ D - Services ■E - Equipment & Furnishings ■F - Special Construction & Demolition G - Sitework

